## MONTANA DIVISION

# "NATIONWIDE" PROGRAMMATIC SECTION 4(f) EVALUATION FOR HISTORIC BRIDGES

Project No.STPP 52-1(18)27, Control No. 4035

Project Name: Bigfork North and South

Date: September 2003

Location: Swan River

This proposed project requires use of a historic bridge structure that is on, or eligible for listing on the NATIONAL REGISTER OF HISTORIC PLACES. The <u>Swan River Bridge</u> carries MT-35 over the Swan River at Bigfork and is located along the shore of Flathead Lake as shown on the attached area map. The present bridge was constructed in 1954 and is comprised of steel plate girders with a non-composite concrete deck. The bridge is a four span configuration spanning the Swan River. The total bridge length is 67.1 meters (220 feet) the clear roadway width 8.5 meters (28 feet). The existing ground slopes underneath the bridge into the water at a rate of approximately 1 1/2:1. The slopes are covered with riprap under the bridge and on the downstream side of the bridge.

Based upon the MDT structure inventory reports the current status of the Swan River Bridge is poor. The general condition of the bridge is rated at about five out of a possible ten in most categories, with on overall sufficiency rating of 49.6. This rating qualifies the bridge for replacement. Several areas needing attention include:

- The deck has extensive cracking, allowing water to penetrate and damage the substructure components.
- Damage to the existing girders has occurred where water has penetrated the paint and caused corrosion.
- The existing bearing devices are out of alignment and need to be repaired.
- Due to insufficient width, there are no facilities for pedestrians and bicycles on the bridge.
- There are currently no expansion devices and the back walls of the abutments are cracking and spalling due to the expansion of the steel girders.
- The are no approach slabs and each end of the structure has a noticeable bump in the road surface due to settlement.
- The bridge parapet does not meet current AASHTO standards.

- The bridge is founded on untreated timber piling of unknown condition.
- The bridge, located in a relatively high seismic zone, does not meet current seismic standards.

		: Any response in a box will require additional information, and ual evaluation/statement. Consult the "Nationwide" Section 4(f) Eval		
1.	Is th	ne bridge a National Historic Landmark?		<u>X</u>
2.	pur	ve agreements been reached through the procedures suant to Section 106 of the National Historic servation Act with the following:		
	STA	TE HISTORIC PRESERVATION OFFICE (SHPO)?	<u>X</u>	
	ADV	VISORY COUNCIL ON HISTORIC PRESERVATION (ACHP)?	_X_	
3.	An	y other agency/ies with jurisdiction at this location?	_X_	
	a)	If "YES" will additional approval(s) for this Section 4(f) application be required?		X
	b)	List of agencies with jurisdiction at this location:		
		USA - CORPS OF ENGINEERS ( <u>Section 404 Stream Crossing Permit necessary</u> ) USDA - Forest Service USDA - Soil Conservation Service ( <i>FPPA</i> ) FEMA Regulatory Floodway ( <u>No Permit necessary</u> ) MDFW&P - Parks Division (Fishing Access Site)( <u>No impact to FAS</u> ) MDFW&P - Wildlife Division (wetlands) MDFW&P - Fisheries Division ( <i>MSPA</i> ) ( <u>Stream Protect Act Permit necessary</u> ) MDNR&C Land Office (navigable rivers under state law) ( <u>Easement for Swan River Crossing</u> )	X 	<u>X</u> <u>X</u>
		MDEQ - Air And Waste Management Bureau		Y

## **ALTERNATIVES & FINDINGS**

MDNR&C (irrigation systems)

**EACH** of the following **ALTERNATIVES** for this proposed project have been evaluated to avoid the use of the historic bridge:

- "Do Nothing."
- 2. Rehabilitate the existing bridge without affecting the historic integrity of the structure in accordance with the provisions of *Section 106* in the *NHPA*.

MDEQ - Water Quality Bureau (318 Authorization necessary)

Rehabilitation is not feasible because of insufficient roadway width to accommodate pedestrian and bicycle needs, and the uncertain condition of untreated wood piles.

3. Construct the proposed bridge at a location where the existing historic structure's integrity will not be affected as determined by the provisions of the *NHPA*.

		Roadway realignment creates substantial impacts to abutting properties and imp	rovements.	
Th E\	ne al	pove ALTERNATIVES have been applied in accordance with this <a href="PROGRAMIJATION">PROGRAMIJATION</a> and are supported by EACH of the following FINDINGS:	MATIC SEC	TION 4(f)
			YES	NO
1.	Th	e "Do Nothing" ALTERNATIVE has been evaluated and has been		
	for	and to ignore the basic transportation need at this location.	_X_	
		is ALTERNATIVE is neither feasible nor prudent for following reasons:		
	a)	Maintenance — this ALTERNATIVE does not correct the structurally deficient condition and/or poor geometrics (clearances, approaches, visibility restrictions) found at the existing bridge. Any of these factors can lead to a sudden catastrophic collapse, and/or a potential injury including loss of life. Normal maintenance will not change this situation.	_X	
	b)	Safety — this <b>ALTERNATIVE</b> also does not correct the situation which causes the existing bridge to be considered deficient. Because of these deficiencies, the existing bridge presents serious and unacceptable safety hazards to the travelling public and/or places intolerable restrictions (gross vehicle weight, height, and/or width) on transport.	_X_	
	А	copy of the MDT Bridge Bureau's Inspection Report is attached.	_X_	
2.		e rehabilitation ALTERNATIVE has been evaluated with one or more the following FINDINGS:		
	a)	The existing bridge's structural deficiency is such that it cannot be rehabilitated to meet minimum acceptable load and traffic requirements without adversely affecting the structure's historic integrity.		
		The condition of untreated wood support piling is unknown.	_X	
	b)			
		The exiting bridge parapet is not an approved crashworthy type.		
		Due to insufficient width pedestrian and bicycle use cannot be accommodated.	_X_	
Al	TF	RNATIVES & FINDINGS (#2 - conclusion:)		
, 11	- ! -	THE TOTAL OF THE PROPERTY OF T	YES	NO
	c)	This <b>ALTERNATIVE</b> does not correct the serious restrictions on visibility (approach geometrics, structural requirements) which also contributes to an unsafe condition at this location.		

N/A

Roadway alignment and geometrics are acceptable.

		his rehabilitation ALTERNATIVE therefore considered to be feasible and/ prudent based on the preceding evaluations?		_X_
3.	as	e relocation <b>ALTERNATIVE</b> , in which the new bridge has been moved to ite that presents no adverse effect upon the existing structure has also en considered under the following <b>FINDINGS</b> :		
	a)	Terrain and/or local geology. The present structure is located at the only feasible and/or prudent site for a bridge on the existing route. Relocating to a new site — either up-, or downstream of the preferred location — will result in extraordinary bridge/approach engineering and associated construction costs.	<u> </u>	
		The preferred site is the <u>only</u> prudent location due to the terrain and/or geologic conditions in the general vicinity.	<u>X</u>	
		Any other location would cause extraordinary disruption to existing traffic patterns.		X
	b)	Significant social, economic and/or environmental impacts. Locating the proposed bridge in other than the preferred site would result in significant social/economic impacts such as the displacement of families, businesses, or severing of prime/unique farmlands.	_X	
		Significant environmental impacts such as the extraordinary involvement in wetlands, regulated floodplains, or habitat of threatened/endangered species are likely to occur in any location outside the preferred site.	<u> </u>	
	c)	Engineering and economics. Where difficulty/ies associated with a new location are less extreme than those listed above, the site may still not be feasible and prudent where costs and/or engineering difficulties reach extraordinary magnitudes. Does the ALTERNATE location result in significantly increased engineering or construction costs (such as a longer span, longer approaches, etc.)?	<u>X</u>	
	d)	Preservation of existing historic bridge may not be possible due to either or both of the following:		
		the existing structure has deteriorated beyond all reasonable possibility of rehabilitation for a transportation or alternative use;	<u>_X</u>	
		no responsible party can be located to maintain and preserve the historic structure.	X	

AL	TERNATIVES & FINDINGS (#3 conclusion:)		
	Therefore, in accordance with the previously-listed FINDINGS it is neither feasible nor prudent to locate the proposed bridge at a site other than the	YES	NO
	preferred ALTERNATE as described.	<u>X</u>	
MI	EASURES TO MINIMIZE HARM		
Ha	is "Nationwide" Programmatic Section 4(f) Statement applies only when the following rm have been assured; a check in a box MAY void the Programmatic application—aluation will be required:		
		YES	NO
1.	Is the bridge being rehabilitated under this proposed project?		_X_
	If "YES", is the historic integrity of the structure being preserved to the greatest extent possible; consistent with unavoidable transportation needs, safety, and load requirements?		
	NOTE: If "NO", refer to item 2., following, to determine Programmatic applicability.		
2.	The bridge is being replaced, or rehabilitated to the point where historic integrity is affected. Are adequate records being made of the existing structure under historic Australia Australia Australia Property and		
	ture under HISTORIC AMERICAN ENGINEERING RECORD standards, or other suitable means developed through consultation with SHPO and the ACHP?	_X_	
3.	If the bridge is being replaced, is the existing structure being made available for alternative use with a responsible party to maintain and preserve same?		50 2000 30
	The existing bridge is not a candidate for adoption, and removal would require demolition.	_	[X]
4.	If the bridge is being adversely affected, has agreement been reached through the Section 106 process of the National Historic Preservation Act on these Measures to Minimize Harm (which will be incorporated into the proposed project) with the following:		
	SHPO on 9/26/2001	<u>X</u>	
	ACHP on10/22/01	X	
	FHWA on 10/2/2001	<u>X</u>	
	A copy of the Programmatic Memorandum of Agreement (P.M.o.A.) signed/approved by these agencies is attached.		

## COORDINATION

There has been additional **COORDINATION** with the following agencies regarding this proposed project (other than those listed previously):

City/County government:

Howard Gite, Flathead County Commissioner, has been a member of the MT-35 Advisory Committee. This committee was organized specifically to address project related issues and community impacts, and has participated the development of the preferred alternative including replacement options for the Swan River Bridge.

Adiacent property owners:

All adjacent property owners are aware of the highway improvement and bridge replacement project through the project public involvement processes. A letter from the Montana Fish, Wildlife and Parks concerning Land and Water conservation funded properties indicates their familiarity with the project.

Date: 10/15/03

Copies of letters from these agencies regarding this proposed project are attached. This proposed project is also documented as a <u>Environmental Assessment</u> under the requirements of the *National Environmental Policy Act* (42 U.S.C. 4321, et seq.).

SUMMARY & APPROVAL - The proposed action meets all criteria regarding the required ALTERNATIVES, FINDINGS, and Measures to Minimize Harm which will be incorporated into this proposed project. This proposed project therefore complies with the July 5, 1983 Programmatic Section 4(f) Evaluation by the U.S. DEPARTMENT OF TRANSPORTATION'S Federal Highway Administration. This document is submitted pursuant to 49 U.S.C. 303 and in accordance with the provisions of 16 U.S.C. 470f.

Jean A. Riley, P.E.

Engineering Section Supervisor
MDT Environmental Services

Approved:


Federal Highway Administration

JAR:SMK:LR7

"Alternate accessible formats of this document will be provided upon request."

Attachments

CC: Loran E. Frazier P.E. – Administrator – MDT Missoula District Carl S. Peil, P.E. – MDT Preconstruction Engineer John H. Horton, Jr. – MDT Right-of-Way Bureau Chief Suzy Althof, P.E. – MDT Contract Plans Section Supervisor David W. Jensen, Supervisor – MDT Fiscal Programming Section Dave Hill - MDT Environmental Services Bureau Chief Susan Kilcrease – MDT Environmental Services w/attachments Joseph P. Kolman, P.E. MDT Bridge Engineer



Page 1 of 6 Form: bms001d

Printing Date: Tuesday, September 23 2003

#### P00052031+00211

Location: BIG FORK Structure Name: none

#### General Location Data

District Code, Number, Location: 01

Dist 1

MISSOULA

State Highway Agency

Division Code, Location:12

KALISPELL

County Code, Location: 029

FLATHEAD

City Code, Location: 00000

Signed Route Number: 00035

RURAL AREA

Kind fo Hwy Code, Description: 3

Str Owner Code, Description: 1

3 State Hwy

Maintained by Code, Description:1

State Highway Agency

Kilometer Post, Mile Post:

49.92 km 30.95

Intersecting Feature: SWAN RIVER

Structure on the State Highway System: X

Latitude: 48°03'30"

Structure on the National Highway System: Str Meet or Exceed NBIS Bridge Length: X Longitude: 114°04'48"

Construction Project Number: F 102-1

Construction Data

Construction Station Number: 1853+50.00

Construction Drawing Number: 3246

Construction Year: 1954

Reconstruction Year:

## Traffic Data

Current ADT: 7,490

ADT Count Year: 2000

Percent Trucks:

### Structure Loading, Rating and Posting Data

#### Loading Data:

Design Loading:		3 MS 13.5 (HS 15)
Inventory Load, Design:	24.4 mton	2 AS Allowable Stress
Operating Load, Design:	24.4 mton	2 AS Allowable Stress
Posting :		5 At/Above Legal Loads

Rating Data:	Operating	Inventory	Posting
Truck Type 1:			
Truck Type 2:			
Truck Type 3:	53		

## Structure, Roadway and Clearance Data

#### Structure Deck, Roadway and Span Data:

Structure Length:

67.06 m

Deck Area:

679.00 m sq

Deck Roadway Width:

8.53 m

Approach Roadway Width:

8.53 m

Median Code, Description: 0 No median

#### Structure Vertical and Horizontal Clearance Data:

Vertical Clearance Over the Structure :

99.99 m

Reference Feature for Vertical Clearance:

N Feature not hwy or RR

Vertical Clearance Under the Structure:

0.00 m

Reference Feature for Lateral Underclearance:

N Feature not hwy or RR

Minimum Lateral Under Clearance Right:

0.00 m

Minimum Lateral Under Clearance Left:

0.00 m

## Span Data

#### Main Span

Number Spans: 4

Material Type Code, Description: 4 Steel continuous

Span Design Code, Description: 2 Stringer/Multi-beam or Girder

Material Type. Code, Description:

Approach Span

Span Design Code, Description:

Deck

Deck Structure Type: 1 Concrete Cast-in-Place

Deck Surfacing Type: 1 Monolithic concrete (concurrently placed with struct

Deck Protection Type: 0 None

Deck Membrain Type: 0 None

(52) Out-to-Out Width:

Number of Spans: 0

10,12 m

Skew Angle: °

(50B) Curb Width:

(50A) Curb Width: 0.00 m

0.00 m

Structure Vertical and Horizontal Clearance Data Inventory Route:

Over / Under Direction	Inventory	South, Ea	ast or Bi-direction	al Travel	North or West Travel		
Name	Route	Direction	Vertical	Horizontal	Direction	Vertical	Horizonta
Route On Structure	P00052	Both	99.99 m	8.53 m	N/A		

No Inspection Work Canadates

## INITIAL ASSESSMENT FORM FOR STRUCTURE:

Page 2 of 6 Form: bms001d

Printing Date: Tuesday, September 23 2003

## P00052031+00211

Continue

Inspection D	ata		n Due Date : 2	-			
Sufficiency Rating: 4 Health Index: 71.72 Structure Status: Not		(91) Inspe	ection Fequency	(months) : 24			
NBI Inspection Da	ata					25-	
(90) Date of Last Insp	pection: 21 August 2	003	ne vi	Las	t Inspected By :Benjamin \	Williamson - 99	
(90) Inspection	on Date :				Inspected By :		
(58) Deck (59) Superstructure (60) Substructure (72) App Rdwy	Rating: 5 Rating: 6 y Align: 7 Unrepaired S	(68) Deck Ge (67) Structure (69) Under Cle (41) Posting	Rating : 5	(36A) B	roach Rail Rating 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(61) Channe (71) Waterway A (113) Scou	rt Rating: N el Rating: 8 Adequacy: 9 or Critical: 4
nspection Hours							
Crew Hours for inspec				per Required :			
Helper H			Snooper Hours		3		
Special Crew Ho			F	lagger Hours :			
Special Equipment Ho	ours:						
Inspection Wor	k Candidates			Effected	Scope of		Covered
Candidate ID	Date Requested	Status	Priority	Structure Unit	Work	Action	Condition States

Page 3 of 6 Form: bms001d

Printing Date: Tuesday, September 23 2003

### P00052031+00211

Continue

Element	Inspection	Data
LICITION	IIISPECTION	Date

Smart Flag	scription										
_	Scale Factor	Env	Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5	
Element 12 -	- Bare Concrete	Deck									
	1	4	679	sq.m.	X	100	0	0		0	(
			******		17.30	%	%	%	9	6	%
Previous Ins	pection Notes :								9		-
some small   09/24/2001 - angles caus 10/13/1999 - minor plow o 09/09/1997 -	potholes (both e - Numerous tran ing bumps at bri - Frequent trans damage to guard - Frequent to exc	nds), see sverse cra dge ends. verse crad angles at	pic. Guard and acks with efflore Minor plow typ cks with efflores both ends. Sli	gles sho scence le dama cence th ght end	ow no signific throughout age to both g hroughout fill settlemen	ant changes. P Medium wear in uard angles. No Some popouts so t at both ends ca	ATCH APPROA wheel paths. A problems noted attered through	wheel paths. App CH ASPHALT AT Approach asphalt dicut. HMWM sea apps at both ends	F BRIDGE END seperating from	S. n guard	
10/01/1994 -	- None							40			
Inspection I	Notes:										
											_
element 107	' - Paint Stl Opn									_	
1	1	2	268	m.		0	0		F	0	C
						%	%	. %	9	6	%
Previous Ins	pection Notes :										
ower flange down to gird	s and webs, insi er area. No sigi	de and ou nificant ch	tside faces abo anges.	ut web :	stiffener con	nections. Deck	construction joir	Mainly at outside its allow moisture	thru at curb cra	acks	
ower flange down to gird 09/24/2001 - construction stiffener in s 10/13/1999 - plates: Utilit 09/09/1997	s and webs, insi er area. No sign - Some paint los joint locations a tiffener, web, an - Some corrosion by attached on let - Crevice corroside - insulation	de and ou nificant ch s throughout t pier loca d lower fla n, paint los fit side, mi sion on up	tside faces abo anges. out with corrosic tions - gap in co anges at all loca as and minor se ssing insulation per flanges with	on and rurb allow tions: Socion los along I	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a	construction joir at top outside of overhand onto g, and minor se ders. Some panchor points, no		d web stiffeners oss at bottom or locations on g om flanges at s st inspection.	acks s at YiCp f irders, plice MUN	
ower flange down to gird 09/24/2001 construction stiffener in s 10/13/1999 plates. Utilit 09/09/1997 downstream	s and webs, insi er area. No sign - Some paint los joint locations a tiffener, web, an - Some corrosion by attached on le - Crevice corrosiside - insulation - None	de and ou nificant ch s throughout t pier loca d lower fla n, paint los fit side, mi sion on up	tside faces abo anges. out with corrosic tions - gap in co anges at all loca as and minor se ssing insulation per flanges with	on and rurb allow tions: Socion los along I	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a	construction joir at top outside of overhand onto g, and minor se ders. Some panchor points, no	girder flanges, an girder. Section I ction loss at othe ck rust along bott change since las	d web stiffeners oss at bottom or locations on g om flanges at s st inspection.	acks s at YES f irders, plice MAD	
ower flange down to gird 09/24/2001 - construction stiffener in s 10/13/1999 - lolates. Utilit 09/09/1997 - downstream 10/01/1994 -	s and webs, insi er area. No sign - Some paint los joint locations a tiffener, web, an - Some corrosion by attached on le - Crevice corrosiside - insulation - None	de and ou nificant ch s throughout t pier loca d lower fla n, paint los fit side, mi sion on up	tside faces abo anges. out with corrosic tions - gap in co anges at all loca as and minor se ssing insulation per flanges with	on and rurb allow tions: Socion los along I	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a	construction joir at top outside of overhand onto g, and minor se ders. Some panchor points, no	girder flanges, an girder. Section I ction loss at othe ck rust along bott change since las	d web stiffeners oss at bottom or locations on g om flanges at s st inspection.	acks s at YiCp f irders, plice MUN	
ower flange down to gird 09/24/2001 construction stiffener in s 10/13/1999 blates. Utilit 09/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sigi - Some paint los joint locations a tiffener, web, an - Some corrosio ty attached on le - Crevice corros side - insulation - None	de and ou nificant ch s through t pier loca d lower fla n, paint los ft side, mi sion on up n failing ne	tside faces abo anges. out with corrosic tions - gap in co anges at all loca as and minor se ssing insulation per flanges with	on and rurb allow tions: Socion los along I	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a	construction joir at top outside of overhand onto g, and minor se ders. Some panchor points, no	girder flanges, an girder. Section I ction loss at othe ck rust along bott change since las	d web stiffeners oss at bottom or locations on g om flanges at s st inspection.	acks s at YiCp f irders, plice MUN	
ower flange down to gird 09/24/2001 construction stiffener in s 10/13/1999 blates. Utilit 09/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sign - Some paint los joint locations a tiffener, web, an - Some corrosion by attached on le - Crevice corrosiside - insulation - None	de and ou nificant ch s throughd t pier loca d lower fla n, paint los ift side, mi sion on up n failing ne	tside faces abo anges. out with corrosic tions - gap in co anges at all loca as and minor se ssing insulation per flanges with	on and rurb allow tions: Socion los along I	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a	construction joir at top outside of overhand onto g, and minor se ders. Some panchor points, no	girder flanges, an girder. Section I ction loss at othe ck rust along bott change since las	d web stiffeners oss at bottom or locations on g om flanges at s st inspection.	acks s at YiCp f irders, plice MUN	
ower flange down to gird 19/24/2001 construction stiffener in s 10/13/1999 blates. Utilit 19/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sigi - Some paint los joint locations a tiffener, web, an - Some corrosio ty attached on le - Crevice corros side - insulation - None	de and ou nificant ch s through t pier loca d lower fla n, paint los ft side, mi sion on up n failing ne	tside faces abo anges. out with corrosic tions - gap in co anges at all loca as and minor se ssing insulation per flanges with	ut web and rurb allow tions. So ction for along I areas	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a	construction joir at top outside of overhand onto g, and minor se ders. Some panchor points, no	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since lase evalent througho	d web stiffeners oss at bottom or locations on g om flanges at s st inspection.	acks s at YECF firders, plice MAD	
ower flange down to gird 19/24/2001 construction stiffener in s 10/13/1999 blates. Utilit 19/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sign - Some paint los joint locations a tiffener, web, an - Some corrosion by attached on le - Crevice corrosiside - insulation - None Notes:	de and ou nificant ch s throughd t pier loca d lower fla n, paint los ift side, mi sion on up n failing ne	tside faces abo anges. out with corrosic tions - gap in co anges at all loca ass and minor se ssing insulation per flanges with ear B-1	ut web and rurb allow tions. So ction for along I areas	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rusting flanges of all gireral locations, a section loss. Lie	at top outside g overhand onto g, and minor se ders. Some pa nichor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	acks s at YECF firders, plice MAD	
ower flange down to gird 09/24/2001 construction stiffener in s 10/13/1999 blates. Utilit 09/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sign - Some paint los joint locations a tiffener, web, an - Some corrosion by attached on le - Crevice corrosiside - insulation - None Notes:	de and ou nificant ch s throughd t pier loca d lower fla n, paint los ift side, mi sion on up n failing ne	tside faces abo anges. out with corrosic tions - gap in co anges at all loca ass and minor se ssing insulation per flanges with ear B-1	ut web and rurb allow tions. So ction for along I areas	stiffener con usting. Som ws moisture Some minor ss along top ength at sev	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a section loss. Lie	at top outside of overhand onto grand minor sed ders. Some parachor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	acks s at Yier f irders, plice MUL	C
ower flange down to gird 19/24/2001 construction stiffener in s 10/13/1999 lates. Utilit 19/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sigi - Some paint los joint locations a tiffener, web, an - Some corrosio y attached on le - Crevice corros side - insulatior - None Notes:	de and ou nificant ch s through t pier loca d lower fla n, paint los fft side, mi sion on up n failing ne	tside faces abo anges. out with corrosic titions - gap in ci anges at all loca ass and minor se ssing insulation per flanges with ear B-1	ut web in and rurb allow tions. Section los along I areas in m.	rusting. Som ws moisture Some minor ss along top ength at sev of beginning	nections. Deck on the minor spalling to drain down of corrosion, rusting flanges of all gireral locations, a section loss. Lie	at top outside of overhand onto grand minor sed ders. Some parachor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	acks s at Yier f irders, plice MUL	C %
ower flange down to gird 09/24/2001 - construction stiffener in s 10/13/1999 - olates. Utilit 09/09/1997 downstream 10/01/1994 - Inspection I	s and webs, insi er area. No sigi - Some paint los joint locations a tiffener, web, an - Some corrosio y attached on le - Crevice corros side - insulatior - None  Notes:  I - Pnt Vrt X-Frai	de and ou nificant ch s through t pier loca d lower fla n, paint los fft side, mi sion on up n failing ne	tside faces abo anges. Out with corrosic tions - gap in control of the corrosic tions - gap in corrosic t	ut web on and rurb allow titions. Section local areas of m.	rusting. Som ws moisture ws moisture Some minor ss along top ength at sev of beginning	nections. Deck on the minor spalling to drain down of corrosion, rusting flanges of all gireral locations, a section loss. Lie	at top outside of overhand onto grand minor sed ders. Some parachor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	acks s at Yier f inders, plice MAIN RIBE	(°
ower flange down to gird 09/24/2001 - 09/24/2001 - 09/24/2001 - 09/24/2001 - 09/09/1997 - downstream 10/01/1994 - Inspection I	s and webs, insi er area. No sigi - Some paint los joint locations a tiffener, web, an - Some corrosio ty attached on le - Crevice corros side - insulation - None  Notes:  1 - Pnt Vrt X-Frai  1  spection Notes: - X-bracing still o - Some paint los	de and ou nificant ch s through t pier loca d lower fla n, paint los ift side, mi sion on up n failing ne	tside faces abo anges. Out with corrosic titions - gap in corrections anges at all local as and minor selections and the selection of the sele	ut web and rourb allow titions. So cition local along I areas a m.  No signature of the sig	stiffener con rusting. Som ws moisture Some minor ss along top ength at sev of beginning	nections. Deck on the minor spalling to drain down of corrosion, rusting flanges of all gireral locations, a section loss. Lie	construction join at top outside of overhand onto g, and minor see ders. Some parachor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	ocks s at YICP finders, plice MULA REF	(°
ower flange down to gird 09/24/2001 construction stiffener in s 10/13/1999 clates. Utilit 09/09/1997 downstream 10/01/1994 Inspection I	s and webs, insi er area. No sigi - Some paint los joint locations a tiffener, web, an - Some corrosio ty attached on le - Crevice corros side - insulation - None  Notes:  1 - Pnt Vrt X-Frai  1  spection Notes: - X-bracing still o - Some paint los	de and ounificant chis throughout pier local discovering the pier local dis	tside faces abo anges. Out with corrosic titions - gap in corrections at all local as and minor selections and minor selections. The selections are selections and minor selections are selections. On, rusting, and are show corrosic anges.	ut web son and rurb allow tions. So ction loo along I areas of m.  No sign minor son and	rusting. Som ws moisture Some minor ss along top ength at sev of beginning	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all girleral locations, a section loss. Lie	construction join at top outside of overhand onto g, and minor see ders. Some parachor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	ocks s at YICP finders, plice MULA REF	0 %
ower flange down to gird 09/24/2001 construction stiffener in s 10/13/1999 clates. Utilit 09/09/1997 downstream 10/01/1994 Inspection I	s and webs, insiler area. No signarea. No some corrosion yeattached on learning and the control of the corrosion of the corrosion. No signarea. No s	de and ounificant chis throughout pier local discovering the pier local dis	tside faces abo anges. Out with corrosic titions - gap in corrections at all local as and minor selections and minor selections. The selections are selections and minor selections are selections. On, rusting, and are show corrosic anges.	ut web son and rurb allow tions. So ction loo along I areas of m.  No sign minor son and	rusting. Som ws moisture Some minor ss along top ength at sev of beginning	nections. Deck on the minor spalling to drain down of corrosion, rustin flanges of all gireral locations, a section loss. Lie	construction join at top outside of overhand onto g, and minor see ders. Some parachor points, no ght corrosion pr	ats allow moisture girder flanges, an girder. Section I ction loss at othe ck rust along bott change since la evalent througho	thru at curb cra d web stiffeners oss at bottom o r locations on g om flanges at s st inspection. ut. Utility on	ocks s at YICP finders, plice MULA REF	0 %

Page 4 of 6 Form; bms001d

Printing Date: Tuesday, September 23 2003

## P00052031+00211

Continue

Element 205 - R/Conc Column  1 3 2 ea. 100 0 0 0  96  Previous Inspection Notes:  18/21/2003 - Minor cracking noted. No problems noted.  19/24/2001 - Some minor cracking of columns at P-3 with cracking of web wall also.  10/13/1999 - Some minor cracking of columns at P-3, not significant. Columns only at P-3, Web wall has +/- 0.5 mm crack thru wall.  19/99/1997 - None  Inspection Notes:  Element 215 - R/Conc Abutment  1 2 29 m. 100 0 0 0  96 96 96 96 96  10/24/2001 - Some minor cracking of abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted.  20/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5.  10/13/1999 - Some minor cracks in abutments. Minor spall of B-5 on right side of right girder, see pic.  20/99/1997 - None  10/01/1994 - None  10/01/1994 - None  10/01/1994 - None  10/01/1994 - R/Conc Cap  1 2 26 m. 100 0 0  96 96 96 96 96 96  Previous Inspection Notes:  Element 234 - R/Conc Cap  1 2 26 m. 100 0 0  97  98  99/24/2001 - Some minor cracking. No changes noted.  10/13/1999 - Some minor cracking. No problems noted.								.) * * * * * *			
1											
Trevious Inspection Notes:  1 3 2 ea. 1000 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				Quantity	Units	Insp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat
Previous Inspection Notes:  8/21/2003 - Minor cracking noted. No problems noted.  9/24/2001 - Some minor cracking of columns at P-3 with cracking of web wall also.  0/13/1999 - Some minor cracking of columns at P-3, not significant. Columns only at P-3. Web wall has +/- 0.5 mm crack thru wall.  9/09/1997 - None  Inspection Notes:											
Previous Inspection Notes:  18/21/2003 - Minor cracking noted. No problems noted.  19/24/2001 - Some minor cracking of columns at P-3 with cracking of web wall also.  10/13/1999 - Some minor cracking of columns at P-3, not significant. Columns only at P-3. Web wall has +/- 0.5 mm crack thru wall.  19/99/1997 - None  Inspection Notes:  1 2 29 m. 100 0 0 0  Previous Inspection Notes:  1 2 29 m. 100 0 0 0  10/24/2001 - Some minor cracking of abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted.  19/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5.  10/13/1999 - Some minor cracks in abutments. Minor spall of B-5 on right side of right girder, see pic.  10/10/1999 - Some minor cracking of abutment components. Minor spall of B-5 on right side of right girder, see pic.  10/10/1999 - Some minor cracking. No problems noted.  1 2 2 26 m. 100 0 0 0 0  1 2 2 6 m. 100 0 0 0  1 3 2 6 m. 100 0 0 0  1 3 2 7 8 m. 100 0 0 0  1 3 2 7 8 m. 100 0 0 0  1 3 2 7 8 m. 100 0 0 0  1 3 2 7 8 m. 100 0 0 0  1 3 2 8 m. 100 0 0 0  1 3 3 9 8 m. 100 0 0 0  1 3 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 3 9 8 m. 100 0 0 0  1 4 9 8 m. 100 0 0 0  1 5 9 8 m. 100 0 0 0  1 5 9 8 m. 100 0 0 0  1 5 9 8 m. 100 0 0 0  1 5 9 8 m. 100 0 0 0  1 6 9 8 m. 100 0 0 0  1 7 9 8 m. 100 0 0 0  1 8 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 100 0 0 0  1 9 9 8 m. 10	11		3		ea.		100	0			
1 2 29 m 100 C Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q							%	%	%	9	
19/24/2001 - Some minor cracking of columns at P-3 with cracking of web wall also.  10/13/1999 - Some minor cracking of columns at P-3, not significant. Columns only at P-3. Web wall has +/- 0.5 mm crack thru wall.  19/99/1997 - None  Inspection Notes:  29 m. 100 0 0 0  29 w 9 w 9 w  20/13/1997 - None  10/13/1999 - Some minor cracking.	revious Inspection	Notes:									
0/13/1999 - Some minor cracking of columns at P-3, not significant. Columns only at P-3. Web wall has +/- 0.5 mm crack thru wall.  1 2 29 m. 100 0 0 0  1 2 29 m. 100 0 0 0  1 3 4 4 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	8/21/2003 - Minor o	cracking i	noted. No	problems not	ed.						3555577
Section Notes:   Sect	9/24/2001 - Some	minor cra	cking of c	olumns at P-3	with cra	cking of web	wall also.				Y.
Inspection Notes:	0/13/1999 - Some	minor cra	cking of c	olumns at P-3	, not sigi	nificant. Col	umns only at P-3	. Web wall has	+/- 0.5 mm crack	thru wall.	
Element 215 - R/Conc Abutment  1 2 29 m. 100 0 0 0  Previous Inspection Notes:  08/21/2003 - Abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted.  19/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at 8-5 - not new - no change. Minor erosion of slope at 8-5.  10/13/1999 - Some minor cracks in abutments. Minor spall of B-5 on right side of right girder, see pic.  10/01/1994 - None  10/01/1994 - None  10/01/1994 - None  10/01/1994 - None  10/01/1999 - Some minor cracking. No changes noted.  10/13/1999 - Some minor cracking. No problems noted.  10/13/1999 - Some minor cracking. No problems noted.  10/13/1999 - Some minor cracking. No problems noted.	9/09/1997 - None										1
1	Inspection Notes:							10010210-10010-000000000000000000000000			
1										-	
1 2 29 m. 100 0 0 0  **Previous Inspection Notes:  18/21/2003 - Abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted.  19/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5.  19/09/1997 - None  10/01/1994 - None  10/01/1994 - None  11 2 26 m. 100 0 0 0  12 26 m. 100 0 0 0  13 20 6 % % % % % % % % % % % % % % % % % %					National Control of the Control						-
Previous Inspection Notes:  18/21/2003 - Abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted.  19/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5.  10/13/1999 - Some minor cracks in abutments. Minor spall of B-5 on right side of right girder, see pic.  10/19/1994 - None  11.	lement 215 - R/Co	nc Abutm	ent								
Previous Inspection Notes:  28/21/2003 - Abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted.  29/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5.  29/24/2001 - Some minor cracks in abutments. Minor spall of B-5 on right side of right girder, see pic.  29/29/19797 - None  20/20/1994 - None  Element 234 - R/Conc Cap  2 26 m. 100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	(1) and 1	1.	2	2	9 m.		100	- 0	0		) -
28/21/2003 - Abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted. 29/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5. 20/13/1999 - Some minor cracks in abutments, Minor spall of B-5 on right side of right girder, see pic. 29/09/1997 - None 29/09/1994 - None 20/001/1994 - None 20/09/29/2001 - Some minor cracking. No changes noted. 20/2012/2003 - Cap shows minor cracking. No changes noted. 20/2013/1999 - Some minor cracking. No problems noted. 20/2013/1999 - Some minor cracking. 20/2013/1999 - Some minor cracking. 20/2013/1999 - None 20/2013/1999 - None	PARTICINES			100-15		100000000000000000000000000000000000000	%	%	%	9	6
28/21/2003 - Abutment components show minor cracking. Spall remains unchanged. Minor erosion. No problems noted. 29/24/2001 - Some minor cracking of abutment components. Minor spall at bottom flange of right girder at B-5 - not new - no change. Minor erosion of slope at B-5. 20/13/1999 - Some minor cracks in abutments, Minor spall of B-5 on right side of right girder, see pic. 29/09/1997 - None 29/09/1994 - None 20/001/1994 - None 20/09/29/2001 - Some minor cracking. No changes noted. 20/2012/2003 - Cap shows minor cracking. No changes noted. 20/2013/1999 - Some minor cracking. No problems noted. 20/2013/1999 - Some minor cracking. 20/2013/1999 - Some minor cracking. 20/2013/1999 - None 20/2013/1999 - None				1							
1 2 26 m. 100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	revious Inspection	Notes:		L	The state of the s						
Element 234 - R/Conc Cap  1 2 26 m. 100 0 0 0 % % % %  Previous Inspection Notes:  08/21/2003 - Cap shows minor cracking. No changes noted.  10/13/1999 - Some minor cracking. No problems noted.  10/13/1999 - Some minor cracking.	8/21/2003 - Abutm 9/24/2001 - Some	ent comp minor cra	SEREFUS							no change. Mir	or
1 2 26 m. 100 0 0 0 0 0 0 0 0 % % % % % % % % % %	8/21/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 9/09/1997 - None	ent comp minor cra 3-5.	icking of a	abutment comp	onents.	Minor spall	at bottom flange	of right girder a		no change. Mir	y. J
1 2 26 m. 100 0 0 0 0 0 0 0 % % % % % % % % % % %	8/21/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None	ent comp minor cra 3-5.	icking of a	abutment comp	onents.	Minor spall	at bottom flange	of right girder a		no change. Mir	И.
1 2 26 m. 100 0 0 0 0 0 0 0 0 % % % % % % % % % %	8/21/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None	ent comp minor cra 3-5.	icking of a	abutment comp	onents.	Minor spall	at bottom flange	of right girder a		no change. Mir	y. J
Previous Inspection Notes:  08/21/2003 - Cap shows minor cracking. No changes noted.  09/24/2001 - Some minor cracking. No problems noted.  10/13/1999 - Some minor cracking.  09/09/1997 - None  10/01/1994 - None	8/21/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None Inspection Notes:	ent comp minor cra 3-5, minor cra	icking of a	abutment comp	onents.	Minor spall	at bottom flange	of right girder a		no change. Mir	И.
Previous Inspection Notes:  08/21/2003 - Cap shows minor cracking. No changes noted.  09/24/2001 - Some minor cracking. No problems noted.  10/13/1999 - Some minor cracking.  09/09/1997 - None  10/01/1994 - None	8/21/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None Inspection Notes:	ent comp minor cra 3-5. minor cra nc Cap	icking of a	abutment comp utments. Mino	onents.	Minor spall	at bottom flange	of right girder a	t B-5 - not new -		M. 31
08/21/2003 - Cap shows minor cracking. No changes noted. 09/24/2001 - Some minor cracking. No problems noted. 10/13/1999 - Some minor cracking. 09/09/1997 - None 10/01/1994 - None	8/21/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None Inspection Notes:	ent comp minor cra 3-5. minor cra nc Cap	icking of a	abutment comp utments. Mino	onents.	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		D
99/24/2001 - Some minor cracking. No problems noted.  10/13/1999 - Some minor cracking.  10/09/1997 - None  10/01/1994 - None	18/21/2003 - Abutm 19/24/2001 - Some 19/24/2001 - Some 19/09/1999 - Some 19/09/1997 - None 19/01/1994 - None Inspection Notes:	ent comp minor cra 3-5. minor cra nc Cap	icking of a	abutment comp utments. Mino	onents.	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		D
10/13/1999 - Some minor cracking. 10/09/1997 - None 10/01/1994 - None	9/24/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 9/09/1997 - None 0/01/1994 - None Inspection Notes:	ent comp minor cra 3-5. minor cra nc Cap 1	icking of a	abutment comp utments. Mino	oonents. or spall o	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		1. A S
0/01/1997 - None 0/01/1994 - None	18/21/2003 - Abutm 19/24/2001 - Some 19/24/2001 - Some 19/09/1999 - Some 19/09/1997 - None 19/09/1994 - None 10/01/1994 - None 10/01/1994 - Repetion Notes:	ent comp minor cra 3-5. minor cra nc Cap 1	cking of a licks in abi	abutment computments. Minc	oonents.  r spall o	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		1. A S
10/01/1994 - None	9/24/2003 - Abutm 9/24/2001 - Some prosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None Inspection Notes: Element 234 - R/Co Previous Inspection 18/21/2003 - Cap sh 19/24/2001 - Some	ent comp minor cra 3-5. minor cra nc Cap 1 Notes :	cking of a ticks in about 2 or cracking. No	abutment computments. Minc	oonents.  r spall o	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		
	9/24/2003 - Abutm 9/24/2001 - Some rosion of slope at E 0/13/1999 - Some 19/09/1997 - None 0/01/1994 - None Inspection Notes: Element 234 - R/Co Previous Inspection 18/21/2003 - Cap sh 19/24/2001 - Some 0/13/1999 - Some	ent comp minor cra 3-5. minor cra nc Cap 1 Notes :	cking of a ticks in about 2 or cracking. No	abutment computments. Minc	oonents.  r spall o	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		
	9/24/2003 - Abutm 9/24/2001 - Some 19/24/2001 - Some 19/09/1997 - Some 19/09/1997 - None 19/09/1994 - None 10/01/1994 - None 10/01/1994 - R/Co 10/01/1994 - R/Co 10/01/1994 - R/Co 10/01/1994 - R/Co 10/01/1997 - Some 19/09/1997 - None	ent comp minor cra 3-5. minor cra nc Cap 1 Notes :	cking of a ticks in about 2 or cracking. No	abutment computments. Minc	oonents.  r spall o	Minor spall	at bottom flange t side of right gir	of right girder a	at B-5 - not new -		

Element Description

## INITIAL ASSESSMENT FORM FOR STRUCTURE:

Page 5 of 6 Form: bms001d Printing Date : Tuesday, September 23 2003

## P00052031+00211

Continue

\* \* \* Span : Main-0 (cont.) \* \* \* \* \* \* \* \*

Smart Flag	Scale Factor	Env	Quantity	Units II	nsp Each	Pct Stat 1	Pct Stat 2	Pct Stat 3	Pct Stat 4	Pct Stat 5
Element 311	- Moveable Bea	aring	-							
	1	2		ea.		0	100	0		
						%	%	%		
Previous Ins	pection Notes :			100000000000000000000000000000000000000	MODEL STORY					The state of the s
08/21/2003 -	Bearings are o	ut of adjus	tment with and	hor bolts o	deflecting.	Some minor cor	rosion and rustin	g. No significar	it changes noted	Salar Sa
							nanges. Corrosio	0.440.700.00000000000000000000000000000		
10/13/1999 <mark>-</mark> Light to med		of adjustm	ent, see pic. Tusting.	hose at P	-2 are tippe		while those at P	A STATE OF THE STA	opposite directi	on. Ma
10/01/1994 -	None									
Inspection N	Notes:			**************************************						
Element 313	- Fixed Bearing								37	
	1	2	- 4	ea.		0	100	0	1000年 建基本	
		4		1676		%	%	%		
Previous Ins	pection Notes :			40.000	THE RESIDENCE					
)8/21/2003 -	Fixed pins at pi	er show so	ome minor con	rosion and	rusting wit	th some minor a	ccumulation abou	ut anchorages.	\$455 E. S. 1911	782.97
09/24/2001 -	P-3 bearings st	now corros	ion and rusting	No cha	nges Nor	problems noted				
	Light to mediu									
	Light to mediun									110
10/01/1994 -										To the
Inspection N	Notes:		SECTION OF STREET		4					
mapecuon r	10103.						10		0	
-								- :		
lement 334	- Metal Rail Co	ated								
	1 -	3	134	m.		O O	0-	100	0	
Marian Sa						%	%	%	%	
Previous Insi	pection Notes :									
08/21/2003 - bridge ends. 09/24/2001 - proximity of t	Rail shows som Bridge rail - sin bridge. Roadwa	gle w-bear y restrictio	m attached to on at bridge, se	old metal t	oridge rail -	Not To Standar	e split and twister d. BAS - NTS, mage along lengtl	Approach rail ol		
09/09/1997 -		Ked and O	I DIOKETI DIOCK	s with som	ie illissing.	winor plow dar	nage along lengti			1 July 1
10/01/1994 -										BEE
Inspection N										
mapecuon N	NOIGS.									



Page 6 of 6 Form: bms001d

Printing Date : Tuesday, September 23 2003

### P00052031+00211 Continue

General Inspection No	ites				
08/21/2003 - None					
09/24/2001 - None					yr :
10/13/1999 - Removed elemen	t 210 because of conversa	ition with Paul Jensen			Mary I
09/09/1997 - None	34.453				
10/01/1994 - Sufficiency Rating Sufficiency Rating Calculation			:36:36		RET
	100 A			ALC: ALC: A	
* .					
					-
4					
			170.000		
		12			

## RECEIVED

SEP 28 2001

ENVIRONMENTAL PROGRAMMATIC AGREEMENT AMONG

THE FEDERAL HIGHWAY ADMINISTRATION
THE ADVISORY COUNCIL ON HISTORIC PRESERVATION
AND

THE MONTANA STATE HISTORIC PRESERVATION OFFICE AFFECTING HISTORIC ROADS AND BRIDGES IN MONTANA

WHEREAS, the Federal Highway Division, Montana Division (FHWA), proposes to make Federal funding available to the Montana Department of Transportation (MDT) for that agency's on-going program to construct or rehabilitate highways and bridges, and

WHEREAS, the FHWA has determined that this federally-assisted program may have an affect upon a certain class of properties included in or eligible for inclusion on the National Register of Historic Places and has consulted with the Advisory Council on Historic Preservation (Council) and the Montana State Historic Preservation Office (SHPO) pursuant to Section 800.14 of the regulations (36 CFR Part 800) implementing Section 106 of the National Historic Preservation Act (16 U.S.C. 470f); and

WHEREAS, the FHWA and the MDT have developed a Historic Preservation Plan (HPP) regarding roads and bridges and that document has been subject to review under 36 CFR 800.14 and has been agreed to by FHWA, SHPO and the Council; and

WHEREAS, this Programmatic Agreement supercedes the original Agreement (implemented July 17, 1997) and the amendment to that Agreement (implemented January 21, 1999); and

WHEREAS, the MDT participated in the consultation and has been invited to concur in this Programmatic Agreement; and

WHEREAS, all references within this Programmatic Agreement are to the Council's regulations that became effective on January 11, 2001;

NOW THEREFORE, the FHWA, the Council, and the Montana SHPO agree that the program addressed in this Programmatic Agreement shall be administered in accordance with the following stipulations to satisfy the FHWA's Section 106 responsibility for all individual undertakings of the program.

## Stipulations

The FHWA will ensure that the following measures are carried out:

1) The FHWA and MDT will comply with 36 CFR §§ 800.4 through 800.6 in regard to determining eligibility of historic-age bridges. The Historic Preservation Plan

- will apply only to those bridges determined eligible for the National Register of Historic Places (NRHP).
- The FHWA and MDT will implement the roads and bridges HPP in lieu of compliance with 36 CFR 800 in regards to trails, roads, and highways in Montana that were constructed after 1859.
- 3) The MDT, in consultation with SHPO, will develop NRHP Multiple Properties Documents regarding specific bridge types to assist the FHWA, SHPO, and MDT in assessing the NRHP eligibility of bridges. The documents will include reinforced concrete, steel stringer, steel girder, and all post-1936 steel truss bridges not included in the MDT's 1985 inventory.
- 4) For all NRHP-eligible bridges offered for adoption under the HPP for which new owners are not found, Historic American Engineering Record (HAER) – level recordation will be completed before the bridge is demolished.
- FHWA will carry out the existing MOA's to preserve or record historic bridges that are now scheduled for replacement.
- 6) The MDT will continue to record and assign Smithsonian trinomial site numbers to segments of historic-age trails, roads, and highway located within the Area of Potential Effect (APE) of the MDT's undertakings. Where particular trail, road and highway segments involve features of historic significance on a statewide or national level, the MDT will consult with SHPO to develop a plan to avoid or incorporate the property into the agency's undertaking as specified in Part VI, Section 4 of the existing Roads and Bridges Historic Preservation Plan (See Attachment One).
- 7) The MDT has acquired a 2± mile (10,560± linear feet) segment of the Mullan Military Road (24MN133) in Mineral County, Montana. The road has been preserved and will be developed as a historic recreational/interpretive trail. The MDT will provide funding toward the development and interpretation of the road and list the segment on the National Register of Historic Places. The interpretive plan for the road will be developed in cooperation with the Montana SHPO, the Lolo National Forest, and the Salish-Kootenai Tribal Preservation Office.
- 8) The MDT will provide funding for the installation of five roadside interpretive markers describing the history and significance of pre-1913 trails and roads that are adjacent to Montana's existing primary and secondary highway system. The marker locations will be determined by MDT and the Montana SHPO.
- 9) This Programmatic Agreement will remain in force for as long as the roads and bridges HPP is in force or unless Stipulation 13 of this Agreement is invoked.

- 10) The MDT will prepare a report biennially on its implementation of the HPP, and provide this report to the FHWA, Montana SHPO, and the Council for review, comment and consultation if needed.
- 11) The Council and the SHPO may monitor activities carried out pursuant to this Programmatic Agreement, and the Council will review such activities if so requested by a signatory to this Agreement or by a member of the public. FHWA will cooperate with the Council and the SHPO in carrying out their monitoring and review responsibilities as stipulated in 36 CFR 800.13.
- 12) Any party to this Programmatic Agreement may request that it be amended, whereupon the parties consult in accordance with 36 CFR 800.13 to consider such an amendment.
- 13) Any party to this Programmatic Agreement may terminate it by providing, in writing, forty-five (45) days notice to the other parties, provided that the parties will consult during the period prior to termination to seek arrangement on amendments or other actions that would avoid termination. In the event of termination, FHWA will comply with 36 CFR Part 800.4 through 800.6 with regard to individual undertakings covered by this Programmatic Agreement.
- 14) Should the Montana SHPO object within sixty (60) days to any action proposed pursuant to this Historic Preservation Plan, the FHWA shall consult with the objecting party to resolve the objection. If the FHWA determines that the objection cannot be resolved, the FHWA shall forward all documentation relevant to the dispute to the Council. Within thirty (30) days after receipt of all pertinent documentation, the Council will either:
  - provide the FHWA and Montana SHPO with recommendations, which the FHWA and Montana SHPO will take into account in reaching a final decision regarding the dispute; or
  - 2. notify the FHWA and Montana SHPO that it will comment pursuant to 36 CFR § 800.6(b), and proceed to comment. Any Council comment provided in response to such a request will be taken into account by the FHWA and Montana SHPO in accordance with 36 CFR § 800.6(c)(2) with reference only to the subject of the dispute; the FHWA and MDT's responsibility to oarry out all actions under this Historic Preservation Plan that are not the subjects of the dispute will remain unchanged.
- 15) At any time during implementation of the measures stipulated in this Agreement and/or Historic Preservation Plan, should any objection to any such measure or its manner of implementation be raised by a member of the public, the FHWA shall take the objection into account and consult as needed with the objecting party, the SHPO or the Council to resolve the objection.

16) In the event that the FHWA does not carry out the terms of this Programmatic Agreement, the FHWA will comply with 36 CFR §§ 800.4 through 800.6 with regard to individual undertakings covered by this Programmatic Agreement.

Execution and implementation of this Programmatic Agreement evidences that the FHWA has satisfied its Section 106 responsibilities for all individual undertakings of the program.

ADVISORY COUNCIL ON HISTORIC PRESERVATION

By: (FOI)

Date: , 1/22/01

MONTANA DIVISION, FEDERAL HIGHWAY ADMINISTRATION

By:

Date: 10-2-2001

MONTANA STATE HISTORIC PRESERVATION OFFICER

CONCUR

MONTANA DEPARTMENT OF TRANSPORTATION

By: