
MONTANA DEPARTMENT OF TRANSPORTATION STREAM MITIGATION MONITORING REPORT

*Mill Creek
Ravalli County, Montana*

*Project Constructed: 2011
Monitoring Report #7: December, 2019*



Prepared for:



Prepared by:



MONTANA DEPARTMENT OF TRANSPORTATION

STREAM MITIGATION MONITORING REPORT #7

YEAR 2019

*Mill Creek
Ravalli County, Montana*

MDT Project Number: NH7-(114)59
Control Number: 2015004

SPA Number: MDT-R2-15-2010
USACE Number: NOW-1997-90821-MTH

Prepared for:

MONTANA DEPARTMENT OF TRANSPORTATION
2701 Prospect Ave
Helena, MT 59620-1001

Prepared by:

Confluence Consulting, Inc.
P.O. Box 1133
Bozeman, MT 59771

December 2019

TABLE OF CONTENTS

1.0	Introduction	1
2.0	Site Location	2
3.0	Monitoring Methods.....	2
4.0	Results	2
4.1.	Riparian Vegetation Inventory-Belt Transects.....	2
4.2.	Bank Erosion Inventory	4
4.2.1.	Erosion Upstream of Monitoring Reach.....	5
4.2.2.	Previously Eroding Bank Segments	5
4.3.	Longitudinal Profile and Perpendicular Transect Surveys	7
5.0	Comparison of Results to Performance Standards	9
5.1.	Riparian Cover	9
5.2.	Bank Erosion Inventory	10
6.0	Literature Cited	11

FIGURES AND TABLES

Figure 1. Project location of Mill Creek Stream Mitigation Site.	3
Figure 2. Site Map of Mill Creek Project Site.....	Appendix A
Figure 3. Weed Observations at the Mill Creek Project Site.....	Appendix A
Table 1. Visual estimate of Mill Creek plant coverage from 2013 through 2019. ..	4
Table 2. Eroding bank summary for Mill Creek observed in 2019.....	7
Table 3. Status of Mill Creek performance standards.	9

APPENDICES

Appendix A - Project Maps
Appendix B - Perpendicular Transect and Longitudinal Profile Plots
Appendix C - Project Site Photos
Appendix D: 2013 – 2019 Comprehensive Plant Species List
Appendix E: 2019 Noxious Weed Species List
Appendix F - As-Built Surveys & Planting Schematics

1.0 INTRODUCTION

The following report presents results for the seventh year of annual post stream re-construction monitoring at the U.S. 93 stream crossing at Mill Creek near Hamilton, Montana. This report includes an evaluation of monitoring results in comparison to performance standards outlined in the approved U.S. Army Corps of Engineers (USACE) 404 permit for the project. Requirements outlined in this permit require a minimum of five years of post-construction monitoring to evaluate compliance toward meeting performance standards. The project was constructed in 2011; therefore, these results provide documentation of the site's condition eight years following the project's completion.

As part of the construction of the Bear Creek Road-South segment of U.S. Highway 93, the Montana Department of Transportation (MDT) relocated a segment of Mill Creek to align with a new permanent bridge. The realignment of Mill Creek included deactivating and filling approximately 630 feet of the channel and constructing approximately 581 feet of new channel through a relic flood swale. Permanent impacts to Mill Creek were authorized by the USACE, as outlined in USACE permit number NWO-1997-90821-MTH and SPA 124 Authorization number MDT-R2-15-2010.

Special conditions specified in this permit included monitoring of the relocated segment of Mill Creek for at least five years following channel construction to document streambank stability and the success of riparian vegetation establishment. Performance success criteria outlined in the monitoring plan for the Mill Creek site include:

1. Riparian vegetation coverage

- a) Minimum of 80% total vegetative coverage by the end of the third growing season.
- b) Minimum of 50% areal coverage by woody species by the end of the third growing season.

2. Streambank stability – any unstable banks within the relocated channel segment will require corrective actions.

Additional reporting requirements outlined in the monitoring plan include:

3. **As-built survey** - as built drawings of the relocated channel at a 1:50 scale or smaller and planting schematic with a planted species list and number of plants planted.
4. **Monitoring stations** - establishment of 4 monitoring stations 75' apart with surveyed cross sections and bank pins installed as permanent reference points.
5. **Photo points** - color photos at each monitoring station showing both banks and upstream and downstream views.

Results of the seventh year monitoring of the Mill Creek project are summarized in Section 4 and compared to performance standards in Section 5. Additional reporting requirements, including project site maps, survey results at four perpendicular transects and a longitudinal profile, project site photographs, 2013 through 2019 comprehensive plant species list, 2019 noxious weed list, 2013 topographic survey of the project site, and planting plan from the approved design are included in appendices as supporting information to document the site's condition.

2.0 SITE LOCATION

The relocated segment of Mill Creek flows beneath a newly constructed bridge on U.S. Highway 93 approximately seven miles north of Hamilton, Montana (Figure 1). The project reach includes approximately 500 feet of Mill Creek upstream of the Highway 93 Bridge and extends approximately 100 feet downstream of the bridge. The project is located in Section 19, Township 7 North, Range 20 West, in Ravalli County, Montana. Note the topographic map in Figure 1 refers to Mill Creek as Fred Burr Creek below the confluence of these streams. The National Hydrography Dataset indicates the project area is on Fred Burr Creek, although the major contributing stream and larger watershed upstream of the confluence of these streams is Mill Creek.

3.0 MONITORING METHODS

Monitoring field crews visited the project site on August 13, 2019 while topographic survey crews visited the site on August 19th, 2019. Field data collection and surveys followed methodologies as described in the 2013 monitoring reports for the Mill Creek site, which may be accessed at:

https://www.mdt.mt.gov/other/webdata/external/planning/STREAM-MITIGATION/2013_REPORTS/2013_MILL_CREEK_MONITORING_REPORT.PDF.

4.0 RESULTS

4.1. Riparian Vegetation Inventory-Belt Transects

Table 1 summarizes the vegetation composition of each riparian transect, including areal percent cover of total vegetation, woody vegetation, and noxious weeds. In 2019, the total percent riparian cover was 88%, and included 58% cover by herbaceous species and 30% cover by woody species. The site exhibited an estimated 14% noxious weed cover, which was similar to that observed during the 2018 monitoring event. Noxious weed infestations were more prevalent on the left (north) bank of the project reach where construction activities occurred. The percent cover estimates recorded for all vegetation categories may have been influenced by a combination of factors, including, but not limited to, adjacent land management, previous herbicide applications, differences in annual precipitation and temperature, fluctuations in plant phenological events in response to climate, and other factors that make it difficult to determine the exact cause(s) for increases or decreases in coverage.




Figure 1. Project location of Mill Creek Stream Mitigation Site.

Table 1. Visual estimate of Mill Creek plant coverage from 2013 through 2019.

Belt Transect	Length (ft)	Total % Riparian Cover							% Woody Cover							% Noxious Weed Cover						
		2013	2014	2015	2016	2017	2018	2019	2013	2014	2015	2016	2017	2018	2019	2013	2014	2015	2016	2017	2018	2019
Right (south bank)	140	100	100	96	97	97	97	97	60	60	60	62	62	63	63	1	1	2	3	3	3	1
Left (north bank)	435	75	80	80	85	80	82	85	15	15	15	16	17	18	20	15	20	25	27	16	17	18
Area weighted Total	575	81	85	84	88	84	86	88	26	26	26	27	28	29	30	11	15	19	21	13	14	14

The vegetation inventory along Mill Creek identified eight noxious weeds and one state-regulated species (Appendix E). Isolated occurrences of houndstongue (*Cynoglossum officinale*), St. Johnswort (*Hypericum perforatum*), and leafy spurge (*Euphorbia esula*) were observed within the project area during the 2017 through 2019 monitoring events, but were not mapped. Noxious weed infestations mapped within the project area ranged from trace (less than 1 percent) to low (1 to 5 percent) cover classes. Locations of all noxious weed infestations, with the exception of isolated weed occurrences, are shown on Figure 3 of Appendix A. Many of these infestations occur on private properties outside of the road right-of-way and are therefore inaccessible to MDT weed contractors.

Appendix D includes a comprehensive list of plant species observed along the new channel alignment and riparian buffer areas from 2013 through 2019. In 2019, 126 species were observed, representing an increase of 4 species since the 2018 monitoring event. Three of the four new species observed in 2019 were native and considered beneficial to the restoration efforts within the project area, as they increase overall species diversity and enhance riparian habitat complexity. These newly observed plant species included western water-hemlock (*Cicuta douglasii*), panicled willowherb (*Epilobium brachycarpum*), and common red raspberry (*Rubus idaeus*). Crested wheatgrass (*Agropyron cristatum*), a species native to Russia and Siberia, was also observed in 2019 within the project area. Sixty of the species (48%) observed between 2013 and 2019 are hydrophytic based on the 2016 National Wetland Plant List (NWPL) (Lichvar *et al.* 2016).

4.2. Bank Erosion Inventory

Over the past seven years, erosion has been observed both upstream and within the project reach, with the extent and severity of erosion documented in each monitoring report. Over this monitoring period, erosion has been attributed to stream bank adjustments resulting from natural scour and depositional processes that occur during and following high flows events. Over the course of the monitoring period (2013-2019), Mill Creek has exhibited mid-channel and point bar depositional features, localized erosion which appears to quickly stabilize, as well as severe erosion just upstream of the project reach. These features are commonly observed in streams that transport large bedload quantities, as is the case for many Bitterroot River tributaries flowing east from the Bitterroot Mountains. In 2019, active bank erosion was noted at four locations within the project reach, and continues to occur along a sharp meander bend immediately upstream of the monitoring reach. Descriptions of erosion at these locations is provided in the following section, while the locations of eroding banks are illustrated on Figure 2 in Appendix A.

4.2.1. *Erosion Upstream of Monitoring Reach.*

Banks EBL1 and EBL2 were originally documented as two separate eroding bank segments that combined into one long, 247-foot eroding bank in 2014 (herein referred to as EBL1-2). This eroding bank occurs on private land upstream of the project reach, but has been documented in previous monitoring reports due to the potential of continued erosion affecting the project reach. The upper 150 feet of EBL1-2 has shown relatively little change over the past four monitoring years, and has shown a bank retreat rate of between 0.2 and 0.6 feet per year (see Additional Photo 1 in Appendix C). The lower 100 feet of the bank has migrated northward at a more rapid pace than the upper bank segment, especially in the vicinity of a large ponderosa pine tree that fell into the channel in 2016. The bank has migrated at a rate of 6-7 feet/year for the past three years adjacent to the exposed root ball of this tree (see Additional Photo 10 in Appendix C).

Bank erosion at EBL1-2 is due to an advancing point bar, which places the channel against a relatively high, herbaceously vegetated stream bank that runs along a relatively sharp meander bend. Root wads and large rocks placed on, but not keyed into the toe of the banks are causing increased scour against the bank toe. The vegetation community along these banks include speckled alder, Kentucky bluegrass, smooth brome, sedges, common yarrow, western-wheat grass, Canadian goldenrod, and ox-eye daisy, most of which are upland species less capable of withstanding erosive forces. The downstream end of the bank retreated at a rate of 1.5 to 3 feet/year from 2013 to 2014, and 3 to 7 feet per year between 2015 and 2018. A 10-foot lateral migration in the past year alone represents the highest rate of erosion noted along this bank since 2013. Based on the combination of eroding factors, severity of erosion along EBL1-2 is considered high, particularly along the lower end of the bank. While erosion rates are high at this location, it has resulted in the recruitment of large woody debris to the channel, which is beneficial toward the development of diverse aquatic habitat.

4.2.2. *Previously Eroding Bank Segments*

Signs of active erosion at EBL3 were originally observed in 2014 at the head of the former channel alignment which is now largely backfilled with gravel, cobble, and soil. As a result, this area is no longer classified as eroding and has been removed from the list of actively eroding banks.

Lateral erosion at bank EBL4 has continued the past four years, as evidenced by a log jam forming adjacent to the bank causing localized scour (see Additional Photo 5 in Appendix C). The bank has retreated approximately one foot in the past year and 9-11 feet in the past six years, although the eroding bank length has actually reduced since the initial bank erosion inventory in 2013. Bank instability at this location was potentially caused by removal of the trees for use in log revetment construction, or by natural channel adjustments and debris jams forming following construction. These debris jams are considered beneficial to the restored channel alignment, as they improve habitat complexity and generate pool scour features to the benefit of fish. The dominant vegetation along the bank includes reed canary grass and smooth brome, the former of

which offers dense roots capable of withstanding erosion more effectively than most species. Erosion severity along this bank is considered low, as it does not jeopardize any infrastructure elements or the newly installed bridge downstream. As a result of the erosion occurring from natural channel adjustments, no corrective actions are warranted at this location.

Eroding bank EBR1 was observed in 2014 and is directly across the channel from EBL4. Previous monitoring efforts documented fallen trees both into the channel and away from the channel along this bank. Continued erosion was not observed along the bank between 2015 and 2017, however minor erosion along the toe of the bank was noted in 2018 (See Additional Photo 6 in Appendix C). No additional erosion was observed in 2019; as such it has been removed from the list of actively eroding banks.

Erosion at EBR2 was originally noted in 2014 along 65 feet of the channel across from the head of the deactivated stream channel. Erosion at this location was tied to channel adjustments and scour along the outside of a meander. Additional erosion along this bank segment was not observed between 2015 and 2017; however the bank showed signs of erosion again in 2018 and 2019, including undercutting, slumping sod mats, and root exposure (see Additional Photo 7 in Appendix C). The eroding bank length doubled from 40 feet to 81 feet in 2019 due to the development of a gravel bar on the north side of the channel, and subsequent scour against the south bank. The erosion is resulting from the natural dynamics of the channel's fluvial processes, and does not need to be corrected despite the eroding bank length doubling in the past year. Movement of the bank is not jeopardizing any infrastructure and is occurring as part of natural channel adjustments. As such, no corrective actions are warranted along this bank.

Eroding bank EBR3 was observed in 2017 adjacent to a woody debris jam and was characterized by upper bank sloughing and toe scour. Vegetation along the upper bank includes reed canary grass, oxeye daisy, woods rose, wheatgrass, brome, small cottonwood saplings, and young willows. The bank appeared to retreat by approximately 1 foot or less during high flows in 2018 or 2019, as the adjacent debris jam broke up and a gravel bar has developed adjacent to the bank (Additional Photo 8 in Appendix C). Given the bank's relatively slow retreat rate and the lack of adjacent infrastructure or fencing, corrective actions are not warranted along this bank at this time.

Erosion was observed in 2018 on the left bank near the upstream end of the monitoring reach (EBL5). Erosion along this 20-foot bank segment is due to gravel depositing on the inside of the meander bend and just below the downed ponderosa pine tree. This deposit focuses high flows toward the left bank, which is primarily vegetated with upland species including short-awn meadow foxtail, white and red clover, Kentucky bluegrass, common tansy, and ox-eye daisy. This bank retreated approximately four feet in 2018, and an additional 10 feet in 2019, as evidenced by bank transect #1. Erosion at this location is now connected to the long eroding bank EBL1-2 described above. This bank has been mapped separately, as it lies within the project reach as opposed to EBL1-2,

which lies upstream of the mitigation area. While the creek has begun to erode into the backfilled area that was the former channel alignment at EBL5, it is not threatening to abandon its existing configuration and overtake the former alignment. The former alignment has been completely backfilled to the height of the surrounding floodplain, and does not provide a preferential flow path for Mill Creek to establish. An updated eroding bank inventory within the Mill Creek project site is summarized as follows:

Table 2. Eroding bank summary for Mill Creek observed in 2019.

Bank Segment ¹	Length (ft)	Bank actively Eroding	Bank no longer eroding
EBL3	30		X
EBL4	36	X	
EBR1	58		X
EBR2	81	X	
EBR3	57	X	
EBL5	20	X	
Total active eroding bank length	194 feet		
Total bank length within project reach	1,450 feet		
Percent of banks actively eroding	13%		

¹ Table does not include EBL1-2, as it lies outside of the project boundary.

4.3. Longitudinal Profile and Perpendicular Transect Surveys

A longitudinal profile of the channel thalweg surveyed each year from 2014 to 2019 and plots for each surveyed transect are included in Appendix B. Transects #2 and #3 were originally installed to document channel dimensions at scour pools formed by woody debris jams, while transects #1 and #4 were surveyed at riffles.

While transect #1 was originally positioned at a riffle, survey data from 2013-2015 indicated the channel transitioned to more of a pool feature by forming a point bar on the left side of the channel and thalweg near the right bank. In 2016, a large ponderosa tree fell into the channel just upstream from transect #1, resulting in a mid-channel gravel bar deposit forming near this transect. In 2017, the mid channel bar further developed, causing a split flow. In 2018, additional deposition closer to the right bank forced flows against the left bank, which scoured a relatively deep pool feature. In 2019, the pool partially filled and the left bank eroded northward roughly 10 feet. Monitoring across this transect over the past seven years depicts an actively adjusting channel due to both depositional and scouring processes, and transitions from pool to riffle features at specific locations (see photos of transect #1 on pages C-13 through C18).

Transect #2 was originally established at a pool adjacent to a woody debris jam formed along the left (north) bank. Between 2015 and 2017, a gravel deposit formed along the left bank which continued to form in 2018, causing the channel thalweg to shift over toward the right bank. This gravel bar has enlarged, creating a pool on the right side of

the channel (see photos of transect #2 on pages C-19 through C22). The shift in thalweg location across the channel at this transect provides additional evidence of the dynamic scour and depositional processes occurring in Mill Creek over time. The adjustment to the channel transect at this location is considered a natural response to frequent gravel deposits and bar development, which is commonly observed in high bedload streams. These adjustments are considered beneficial to the channel over time, as they provide a diversity in habitat complexity within the active channel.

In 2017, a deep pool developed at transect #3 adjacent to a woody debris jam. This pool has maintained itself over the past two years due to scour against the adjacent woody debris jam (see photos of transect #2 on pages C-23 through C26). The pool here is three feet deeper than it was in 2016, and has remained the deepest pool within the project reach for the past three years.

Transect #4 was originally positioned at a riffle just above the last meander bend upstream of the U.S. Highway 93 Bridge. A point bar has continuously developed on the left bank, with deeper thalweg along the right bank. As a result, this transect has developed into a shallow pool. Bar development along the left bank may eventually result in erosion along the right bank; however no erosion has been observed in the vicinity of transect #4 to date (see photos of transect #2 on pages C-27 through C30).

Inspection of the stream bed longitudinal profile and cross sections at each of the four monitoring transects over the past seven years reveal a stream bed that is adjusting over time to incoming sediment loads and woody debris complexes and the continued presence of both pool and riffle features. Mill Creek exhibits active bedload transport, as evidenced by the frequency of point bars and a thalweg that shifts from one side of the channel to the other. The adjusting banks and bed within the monitoring reach provide evidence that the channel is naturally adjusting to fluvial processes during and following high flow events. Given the channel is actively moving but does not threaten infrastructure, efforts to stabilize banks or prevent naturally active bed movements are unwarranted. Allowing the channel to freely adjust and migrate has resulted in the development of several high-quality features, including deep scour pools and riffles that provide productive and diverse habitat that benefit aquatic species.

The longitudinal profile of the channel indicates the presence of several pool and riffle features, which are adjusting spatially as the channel reacts to incoming gravel and woody debris. Two deep pools exist within the project reach, both of which have been observed to hold schools of trout. Five shallower pools exist, and are formed by scour against the stream banks and smaller debris. Overall, the project reach indicates a healthy diversity of aquatic habitat features, and has remained stable since 2014. No signs of aggradation or degradation exist, and the reconstructed channel appears to be maintaining a relatively consistent gradient since monitoring efforts began.

5.0 COMPARISON OF RESULTS TO PERFORMANCE STANDARDS

Monitoring of the Mill Creek Stream Mitigation site is intended to document whether the reconstructed segment of the channel is meeting performance standards outlined in the approved U.S. Army Corps permit for the project. Table 3 summarizes the status of each performance criteria following the seventh year of monitoring and eight years following completion of the project. Additional reporting requirements, including results of the perpendicular transects, bed profile survey, photo-documentation, and as-built topographic schematics are included as appendices to this report and offer additional documentation of the site's current condition.

Table 3. Status of Mill Creek performance standards.

Parameter	Success Criteria	Status	Meeting Performance Criteria?
Riparian Cover	80% total vegetative coverage after 3rd year	Total vegetative cover of the project site is 88% following the sixth year of monitoring (97% of south bank and 85% of north bank).	YES
	50% woody species coverage after 3rd year	Woody cover of the project site is 30% following the sixth year of monitoring (63% of south bank and 20% of north bank).	NO
Streambank Stability	Unstable banks identified within the project reach will require corrective action	Four eroding bank segments were observed in 2019 totaling 194 feet, or 13% of the total bank length within the project reach. Given these banks are adjusting due to natural scour and depositional processes and do not threaten infrastructure, corrective actions do not appear warranted.	YES

5.1. Riparian Cover

Vegetation along the south bank of Mill Creek was minimally disturbed during construction of the new channel alignment and was limited to a short (approximately 50') reach immediately adjacent to the new highway bridge. This channel segment has been stabilized with rock to protect the bridge infrastructure. Woody vegetation establishment along the north bank has yet to develop as planned.

Total vegetation cover observed along the north bank riparian transect was 85%. Areas of bare ground were observed along the deactivated channel alignment and within and adjacent to noxious weed infestations. A mowed, two-track road was observed within the north bank riparian area, running from the private property to the west through the mitigation area to the bridge, which is resulting in a reduction in total percent cover within the riparian transect. Vegetation within the restored channel reach is now dominated by native and non-native grass and forb species, with minimal cover by volunteer woody species. An increase in perennial grass cover (e.g., *Poa compressa*, *Festuca idahoensis*) and volunteer woody cover (e.g., *Pinus ponderosa*, *Rosa woodsii*, *Populus balsamifera*) were observed beneath many of the mature ponderosa pine trees, adding to the overall habitat complexity within this area along the north bank. When factoring in the undisturbed south bank, total vegetation cover across the site was 88%, which exceeds the 80% success threshold for riparian cover throughout the site.

Woody vegetation cover along the north bank was estimated at 20% cover, which falls well below the success criteria threshold of 50%. While no woody vegetation was

observed along the backfilled channel segment, there was a minimal increase in woody shrubs and saplings observed along the north bank of the newly aligned channel. Several mature ponderosa pine trees remain along the north bank and provide the majority of the woody species composition. Woody vegetation cover along the south bank was estimated at 63%. The area weighted average of woody vegetation cover for the north and south bank belt transects was 30%. Woody vegetation cover meets the performance criterion along the south bank but does not along north bank.

5.2. Bank Erosion Inventory

Four eroding banks were observed within the project reach totaling 194 feet, or 13% of the total bank length. Locations of eroding bank and eroding bank length over the past seven years have fluctuated due to gravel bar deposition, woody debris, and adjusting riffle locations. Woody debris jams have continued to influence bank erosion where large trees have fallen into the channel and generate scour. None of the erosion threatens highway infrastructure or fences and is occurring due to natural fluvial processes of deposition and scour.

Eroding bank EBL1-2 has continued to advance northward, particularly near the downstream end of the eroding bank. Erosion along this bank has resulted in a large ponderosa pine tree falling into the channel in 2016, which has induced additional scour in the vicinity of the root ball and trunk. The bank has retreated northward approximately 20 feet in the past three years near the downed tree, but otherwise has not jeopardized the project reach or any infrastructure. The fallen tree has resulted in more diverse habitat and the development of a deep pool immediately downstream. While the erosion is more pronounced along the downstream end of EBL1-2 and at EBL5, the creek is not threatening to overtake the former channel alignment, which has been completely backfilled. The former channel alignment has been filled to match the surrounding floodplain elevations, and is currently functioning as such.

The severity of bank erosion within the project reach is considered low due to relatively slow bank migration rates occurring as a result of natural processes that do not currently jeopardize infrastructure. Erosion along the banks within the project reach are due to processes that occur in naturally functioning channels with high bedload and snowmelt driven hydrology. Bedload deposition and scour created by meander bends and woody debris will continue resulting in minor lateral movement of the stream banks. Given the degree of active erosion currently observed, corrective actions do not seem warranted at this time.

6.0 LITERATURE CITED

Elzinga, C.L., D.W. Salzer, and J.W. Willoughby. 1998. *Measuring and monitoring plant populations*. Bureau of Land Management (BLM) Technical Reference 1730-1. Washington, DC: U.S. Department of the Interior.

Lichvar, R.W., D.L. Banks, W.N. Kirchner, and N.C. Melvin. 2016. *The National Wetland Plant List: 2016 Update of Wetland Ratings*. Phytoneuron 2016-30: 1-17. Published 28 April 2016. ISSN 2153 733X

Websites

Montana Department of Agriculture. *Montana Noxious Weed List*. June 2019.

Accessed October 2019 at:

<https://agr.mt.gov/Portals/168/Documents/Weeds/2019%20Montana%20Noxious%20Weed%20List.pdf?ver=2019-07-02-095540-487>

USDA, NRCS. 2019. *The PLANTS Database*. National Plant Data Team, Greensboro, NC 27401-4901 USA. Accessed October 2019 at: <http://plants.usda.gov>

Appendix A

Project Maps


MDT Stream Mitigation Monitoring
Mill Creek
Ravalli County, Montana

Appendix B


Longitudinal Profile and Perpendicular Transect Plots

MDT Stream Mitigation Monitoring
Mill Creek
Ravalli County, Montana


Mill Creek Transect #1 - Riffle




Mill Creek Transect #2 - Pool




Mill Creek Transect #3 - Pool



Mill Creek Transect #4 - Riffle



Mill Creek Longitudinal Profiles: 2014 and 2019



Appendix C

Project Site Photos

MDT Stream Mitigation Monitoring
Mill Creek
Ravalli County, Montana

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 1.1: View east (downstream) of Hwy 93 Bridge. **Compass:** 45 (Northeast)



2013



2019

Photo Point 1.2: View from southeast corner of bridge looking downstream. **Compass:** 45 (Northeast)



2013



2019

Photo Point 2.1: View across channel from west side of bridge. **Compass:** 113 (East-Southeast)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 2.2: View from west side of bridge looking across stream channel. **Compass:** 225 (Southwest)



2013



2019

Photo Point 2.3: View from Photo Point 2 looking upstream. **Compass:** 248 (West-Southwest)



2013



2019

Photo Point 2.4: View of deactivated channel alignment **Compass:** 270 (West)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 2.5: View of deactivated channel alignment. **Compass:** 248 (West-Southwest)



2013



2019

Photo Point 3.1: View of deactivated channel segment from Photo point 3. **Compass:** 68 (East-Northeast)



2013



2019

Photo Point 3.2: View of deactivated channel plug. **Compass:** 45 (East)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 3.3: View of deactivated channel plug from Photo Point 3. **Compass:** 0 (North)



2013



2019

Photo Point 3.4: View of deactivated channel plug from Photo Point 3. **Compass:** 315 (Northwest)



2013



2019

Photo Point 3.5: View of upstream extent of deactivated channel segment **Compass:** 270 (West)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 3.6: View of north bank (foreground) and woody debris in the channel. **Compass:** 248 (WSW)



2013



2019

Photo Point 3.7: View of north bank (foreground) and woody debris in the channel. **Compass:** 180 (South)



2013



2019

Photo Point 3.8: View looking across deactivated channel segment. **Compass:** 90 (East)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 4.2: View across stream channel toward south bank. **Compass:** 180 (South)
Note: toppled Ponderosa pine tree obscures view on left side of photo



2013



2019

Photo Point 4.3: View of point bar formation from Photo Point 4. **Compass:** 225 (Southwest)



2013



2019

Photo Point 4.4: View of boulders, logs, and root wads placed on bank. **Compass:** 248 (West-Southwest)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Photo Point 5.1: View looking upstream of south bank taken from bridge. **Compass:** 248 (West-Southwest)



2013



2019

Photo Point 5.2: View looking upstream from bridge. **Compass:** 203 (South-Southwest)



2013



2019

Photo Point 5.3: View looking upstream from bridge. **Compass:** 203 (South-Southwest)

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Additional Photo 1: Upper end of eroding Bank EBL1 -2

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Additional Photo 2: Lower end of eroding Bank EBL1-2

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2014 and 2019 Monitoring Events



2014



2019

Additional Photo 3: Upper section of Eroding Streambank EBL3

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2014 and 2019 Monitoring Events



2014



2019

Additional Photo 4: Lower section of Eroding Streambank EBL3

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2013 and 2019 Monitoring Events



2013



2019

Additional Photo 5: Eroding streambank EBL4



2013



2019

Additional Photo 6: Eroding streambank EBR1



2013



2019

Additional Photo 7: Eroding streambank EBR2

PHOTO INFORMATION

PROJECT NAME: Mill Creek Stream Mitigation Site

DATE: 2016 - 2019 Monitoring Events



2018



2019

Additional Photo 8: Eroding Bank EBR3



2018



2019

Additional Photo 9: Eroding bank EBL5



2016



2019

Additional Photo 10: Ponderosa pine in channel near downstream end of EBR2



PHOTOGRAPHIC INSPECTION INFORMATION

Page 1 of 16

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T1 LOOKING NORTH UPSTREAM FROM T1 SOUTH



T1 LOOKING SOUTH DOWNSTREAM FROM T1 NORTH

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T1 LOOKING WEST UPSTREAM FROM SOUTH BANK



T1 LOOKING EAST DOWNSTREAM FROM SOUTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T1 LOOKING WEST UPSTREAM FROM MIDDLE OF CREEK



T1 LOOKING EAST DOWNSTREAM FROM MIDDLE OF CREEK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T1 LOOKING WEST UPSTREAM FROM NORTH BANK



T1 LOOKING EAST DOWNSTREAM FROM NORTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T2 LOOKING NORTH UPSTREAM FROM T2 SOUTH



T2 LOOKING SOUTH DOWNSTREAM FROM T2 NORTH

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T2 LOOKING WEST UPSTREAM FROM SOUTH BANK



T2 LOOKING EAST DOWNSTREAM FROM SOUTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T2 LOOKING WEST UPSTREAM FROM MIDDLE OF CREEK



T2 LOOKING EAST DOWNSTREAM FROM MIDDLE OF CREEK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T2 LOOKING WEST UPSTREAM FROM NORTH BANK



T2 LOOKING EAST DOWNSTREAM FROM NORTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T3 LOOKING SOUTH UPSTREAM FROM T3 NORTH



T3 LOOKING SOUTH DOWNSTREAM FROM T3 SOUTH

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T3 LOOKING WEST UPSTREAM FROM SOUTH BANK



T3 LOOKING EAST DOWNSTREAM FROM SOUTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T3 LOOKING WEST UPSTREAM FROM MIDDLE OF CREEK



T3 LOOKING EAST DOWNSTREAM FROM MIDDLE OF CREEK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T3 LOOKING WEST UPSTREAM FROM NORTH BANK



T3 LOOKING EAST DOWNSTREAM FROM NORTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T4 LOOKING NORTH UPSTREAM FROM T4 SOUTH



T4 LOOKING SOUTH DOWNSTREAM FROM T4 NORTH

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T4 LOOKING WEST UPSTREAM FROM SOUTH BANK



T4 LOOKING EAST DOWNSTREAM FROM SOUTH BANK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T4 LOOKING WEST UPSTREAM FROM MIDDLE CREEK



T4 LOOKING EAST DOWNSTREAM FROM MIDDLE CREEK

PROJECT NAME: 2019 MDT STREAM MITIGATION—MILL CREEK
DATE: 8-19-19



T4 LOOKING WEST UPSTREAM FROM NORTH BANK



T4 LOOKING EAST DOWNSTREAM FROM NORTH BANK

Appendix D

2013 – 2019 Comprehensive Plant Species List

MDT Stream Mitigation Monitoring
Mill Creek
Ravalli County, Montana

Comprehensive list of plant species observed at the Mill Creek Stream Mitigation Site from 2013 through 2019.

Scientific Name	Common Name	WMVC Indicator Status*	Scientific Name	Common Name	WMVC Indicator Status*
<i>Achillea millefolium</i>	Common Yarrow	FACU	<i>Juncus balticus</i>	Baltic Rush	FACW
<i>Agropyron cristatum</i>	Crested Wheatgrass	UPL	<i>Juncus effusus</i>	Lamp Rush	FACW
<i>Agrostis gigantea</i>	Black Bent	FAC	<i>Juncus ensifolius</i>	Dagger-Leaf Rush	FACW
<i>Agrostis scabra</i>	Rough Bent	FAC	<i>Juncus</i> sp.	Rush	N/A
<i>Agrostis stolonifera</i>	Spreading Bent	FAC	<i>Juncus tenuis</i>	Lesser Poverty Rush	FAC
<i>Algae, brown</i>	Algae, brown	N/A	<i>Juniperus scopulorum</i>	Rocky Mountain Juniper	UPL
<i>Algae, green</i>	Algae, green	N/A	<i>Lactuca serriola</i>	Prickly Lettuce	FACU
<i>Alnus incana</i>	Speckled Alder	FACW	<i>Lepidium campestre</i>	Field Pepper-Grass	UPL
<i>Alopecurus aequalis</i>	Short-Awn Meadow-Foxtail	OBL	<i>Leucanthemum vulgare</i>	Ox-Eye Daisy	FACU
<i>Alyssum alyssoides</i>	Pale Alyssum	UPL	<i>Lolium perenne</i>	Perennial Rye Grass	FAC
<i>Amelanchier alnifolia</i>	Saskatoon Service-Berry	FACU	<i>Lotus corniculatus</i>	Garden Bird's-Foot-Trefoil	FAC
<i>Antennaria parvifolia</i>	Nuttall's Pussytoes	UPL	<i>Lupinus sericeus</i>	Pursh's Silky Lupine	UPL
<i>Artemisia absinthium</i>	Absinthium	UPL	<i>Lycopus asper</i>	Rough Water-Horehound	OBL
<i>Aster</i> sp.	Aster	N/A	<i>Maianthemum stellatum</i>	Starry False Solomon's-Seal	FAC
<i>Bassia scoparia</i>	Burningbush	FAC	<i>Medicago lupulina</i>	Black Medick	FACU
<i>Berteroa incana</i>	Hoary False-Alyssum	UPL	<i>Meibotus officinalis</i>	Yellow Sweet-Clover	FACU
<i>Betula pumila</i>	Bog Birch	OBL	<i>Mentha arvensis</i>	American Wild Mint	FACW
<i>Bromus arvensis</i>	Field Brome	UPL	<i>Mimulus guttatus</i>	Seep Monkey-Flower	OBL
<i>Bromus inermis</i>	Smooth Brome	UPL	<i>Myosotis laxa</i>	Bay Forget-Me-Not	OBL
<i>Bromus japonicus</i>	Japanese Brome	UPL	<i>Oenothera villosa</i>	Hairy Evening-Primrose	FAC
<i>Bromus tectorum</i>	Cheatgrass	UPL	<i>Onopordum acanthium</i>	Scotch Thistle	UPL
<i>Calamagrostis canadensis</i>	Bluejoint	FACW	<i>Pascopyrum smithii</i>	Western-Wheat Grass	FACU
<i>Calamagrostis stricta</i>	Slim-Stem Reed Grass	FACW	<i>Persicaria amphibia</i>	Water Smartweed	OBL
<i>Camelina microcarpa</i>	Little-Pod False Flax	FACU	<i>Persicaria</i> sp.	Smartweed	N/A
<i>Carduus nutans</i>	Nodding Plumeless-Thistle	UPL	<i>Phalaris arundinacea</i>	Reed Canary Grass	FACW
<i>Carex aquatilis</i>	Leafy Tussock Sedge	OBL	<i>Phleum pratense</i>	Common Timothy	FAC
<i>Carex bebbii</i>	Bebb's Sedge	OBL	<i>Pinus ponderosa</i>	Ponderosa Pine	FACU
<i>Carex nebrascensis</i>	Nebraska Sedge	OBL	<i>Plantago major</i>	Great Plantain	FAC
<i>Carex</i> sp.	Sedge	N/A	<i>Poa compressa</i>	Flat-Stem Blue Grass	FACU
<i>Carex stipata</i>	Stalk-Grain Sedge	OBL	<i>Poa palustris</i>	Fowl Blue Grass	FAC
<i>Carex utriculata</i>	Northwest Territory Sedge	OBL	<i>Poa pratensis</i>	Kentucky Blue Grass	FAC
<i>Centaurea stoebe</i>	Spotted Knapweed	UPL	<i>Populus angustifolia</i>	Narrow-Leaf Cottonwood	FACW
<i>Cerastium arvense</i>	Field Mouse-Ear Chickweed	FACU	<i>Populus balsamifera</i>	Balsam Poplar	FAC
<i>Chamaenerion angustifolium</i>	Narrow-Leaf Fireweed	FACU	<i>Prunella vulgaris</i>	Common Selfheal	FACU
<i>Cicuta douglasii</i>	Western Water-Hemlock	OBL	<i>Pseudoroegneria spicata</i>	Bluebunch Wheatgrass	UPL
<i>Cirsium arvense</i>	Canadian Thistle	FAC	<i>Ranunculus aquatilis</i>	White Water-Crowfoot	OBL
<i>Cirsium vulgare</i>	Bull Thistle	FACU	<i>Ranunculus repens</i>	Creeping Buttercup	FAC
<i>Collomia linearis</i>	Narrow-Leaf Mountain-Trumpet	FACU	<i>Ranunculus</i> sp.	Buttercup	N/A
<i>Cornus alba</i>	Red Osier	FACW	<i>Ribes lacustre</i>	Bristly Black Gooseberry	FAC
<i>Crataegus douglasii</i>	Black Hawthorn	FAC	<i>Rosa woodsii</i>	Woods' Rose	FACU
<i>Cynoglossum officinale</i>	Gypsy-Flower	FACU	<i>Rubus idaeus</i>	Common Red Raspberry	FACU
<i>Dactylis glomerata</i>	Orchard Grass	FACU	<i>Rumex acetosella</i>	Common Sheep Sorrel	FACU
<i>Dasiphora fruticosa</i>	Golden-Hardhack	FAC	<i>Rumex crispus</i>	Curly Dock	FAC
<i>Deschampsia caespitosa</i>	Tufted Hairgrass	FACW	<i>Salix bebbiana</i>	Gray Willow	FACW
<i>Descurainia sophia</i>	Herb Sophia	UPL	<i>Salix exigua</i>	Narrow-Leaf Willow	FACW
<i>Eleocharis palustris</i>	Common Spike-Rush	OBL	<i>Salix lasiandra</i>	Pacific Willow	FACW
<i>Elymus canadensis</i>	Nodding Wild Rye	FAC	<i>Scirpus microcarpus</i>	Red-Tinge Bulrush	OBL
<i>Elymus glaucus</i>	Blue Wild Rye	FACU	<i>Silene vulgaris</i>	Maiden's-tears	UPL
<i>Elymus repens</i>	Creeping Wild Rye	FAC	<i>Sisymbrium altissimum</i>	Tall Hedge-Mustard	FACU
<i>Epilobium brachycarpum</i>	Panicled Willowherb	UPL	<i>Solanum dulcamara</i>	Climbing Nightshade	FAC
<i>Epilobium ciliatum</i>	Fringed Willowherb	FACW	<i>Solidago canadensis</i>	Canadian Goldenrod	FACU
<i>Equisetum arvense</i>	Field Horsetail	FAC	<i>Sonchus arvensis</i>	Field Sow-Thistle	FACU
<i>Equisetum hyemale</i>	Tall Scouring-Rush	FACW	<i>Symphoricarpos albus</i>	Common Snowberry	FACU
<i>Erodium cicutarium</i>	Stork's Bill	UPL	<i>Symphyotrichum laeve</i>	Smooth Blue American-Aster	FACU
<i>Euphorbia esula</i>	Leafy Spurge	UPL	<i>Tanacetum vulgare</i>	Common Tansy	FACU
<i>Festuca idahoensis</i>	Bluebunch Fescue	FACU	<i>Taraxacum officinale</i>	Common Dandelion	FACU
<i>Filago arvensis</i>	Field Fluffweed	UPL	<i>Thinopyrum intermedium</i>	Intermediate Wheatgrass	UPL
<i>Fragaria virginiana</i>	Virginia Strawberry	FACU	<i>Thlaspi arvense</i>	Field Pennycress	UPL
<i>Glyceria striata</i>	Fowl Manna Grass	OBL	<i>Tragopogon pratensis</i>	Meadow Goat's-beard	UPL
<i>Geum macrophyllum</i>	Large-Leaf Avens	FAC	<i>Trifolium pratense</i>	Red Clover	FACU
<i>Geum</i> sp.	Avens	N/A	<i>Trifolium repens</i>	White Clover	FAC
<i>Holcus lanatus</i>	Common Velvet Grass	FAC	<i>Verbascum thapsus</i>	Great Mullein	FACU
<i>Hypericum perforatum</i>	Common St. John's-Wort	FACU	<i>Veronica americana</i>	American-Brooklime	OBL

* 2016 National Wetland Plant List; Western Mountains, Valleys, and Coast Region (WMVC) (Lichvar *et al.* 2016)

New species identified in 2019 are **bolded**

Species identified to genus level have been assigned an indicator status of N/A

Appendix E

2019 Noxious Weed Species List

MDT Stream Mitigation Monitoring
Mill Creek
Ravalli County, Montana

Montana State listed noxious weed and regulated species observed in 2019 at the Mill Creek Stream Mitigation Site.

Category*	Scientific Name	Common Name
Priority 2B	<i>Berteroa incana</i>	Hoary Alyssum
	<i>Centaurea stoebe</i>	Spotted Knapweed
	<i>Cirsium arvense</i>	Canada Thistle
	<i>Cynoglossum officinale</i>	Houndstongue
	<i>Hypericum perforatum</i>	St. Johnswort
	<i>Euphorbia esula</i>	Leafy Spurge
	<i>Leucanthemum vulgare</i>	Oxeye Daisy
	<i>Tanacetum vulgare</i>	Common Tansy
Priority 3 State Regulated	<i>Bromus tectorum</i>	Cheatgrass

* Based on the MT Department of Agriculture 2019 Noxious Weed List

Appendix F

As-Built Surveys & Planting Schematics

MDT Stream Mitigation Monitoring
Mill Creek
Ravalli County, Montana

