

A CADD Application Enhancement/Work Request may be submitted for new MDT Civil 3D State Kit development needs. Use the Submit a Request link on the Submit a Requ

For Review For Assignment In Development Testing

For Review (63)	For Assignment (4)	In Development (3)	Ready for Testing / Testing (0)	State Kit N/A (12)

Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		Excel Manager Automation-SISUM Priority: HIGH The SISUM Excel tool will need "Place" functionality to work in Civil 3D for Signing summary sheet process.	Email Task Team	In Development
2024.4	State Kit (vX.XX)	TBD	State Kit Documentation Priority: MEDIUM New/updated 2022 state kit documentation. Documents to be created with Montana "branded" template.	Email Task Team	In Development
2024.4	State Kit (vX.XX)	TBD	State Kit Files Map Priority: HIGH, Complexity: MODERATE Need a map charting contents of state kit files.	Email Task Team	In Development
2024.4	State Kit (vX.XX)	TBD	Block Layers and Fonts: EL-Standard Details [Electrical Detail Block Layer Use] Priority: LOW, Complexity: COMPLEX Block layers don't follow layer naming convention or use Arial font.	Email Task Team	For Assignment
2024.4	State Kit (vX.XX)	TBD	Block Layers and Fonts: Layouts Priority: LOW, Complexity: MODERATE Block layers don't follow layer naming convention or use Arial font.	Email Task Team	For Assignment
2024.4	State Kit (vX.XX)	TBD	Block Layers and Fonts: SU-Cadastral Priority: LOW, Complexity: COMPLEX Block layers don't follow layer naming convention or use Arial font.	Email Task Team	For Assignment
2024.4	State Kit (vX.XX)	TBD	Block Layers and Fonts: EL-Plan Priority: LOW, Complexity: COMPLEX Block layers don't follow layer naming convention or use Arial font.	Email Task Team	For Assignment



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		2024 Update Reference Templates Tool Priority: HIGH, Complexity: COMPLEX 2022 reference template paths may need to be updated for 2024 state kit pathing. Need to automate or semi-automate reference template path updating.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Excel Tools-Electrical Priority: HIGH Excel is used for summary and ownership table data to be inserted into drawing files. Need a location and delivery method within or separate from the state kit.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Custom Routine to Scale DGN Converted Elements Priority: HIGH DGN converted surveys result in linetype symbology and point symbols having fixed scale.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Exhibit FHWA/MDT APPROVAL and MAP REVISED dates Priority: HIGH FHWA/MDT APPROVAL and MAP REVISED dates are displayed on the Right-of-Way exhibit sheet.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	R/W View Frame Styles [R/W Viewport limits and View Frame Styles - State Kit needs, R/W View Frame Limits, View Frame Styles] Priority: MEDIUM, Complexity: SIMPLE R/W plans have a wider vertical plan area than referenced in plan and profile sheets. A method is needed to show reference lines to place plan and profile consumable data while maintaining wider view frame lines for r/w sheets.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Alignment and Profile Design Check Styles Priority: MEDIUM Need Design Check Styles for profiles to support MDT processes.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Alignment Command Settings Priority: MEDIUM Alignment command settings are needed to set default layers and styles.	Email Task Team	For Review



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		Bentley Layer Translator-Road Design Priority: MEDIUM Files converted from DGN to DWG are not appropriately mapping Bentley levels to new Civil3D layer names for Road Design Data.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Corrections to Parts Catalog Priority: MEDIUM The wall thicknesses of the CSP pipes do not match the detailed dwgs. The CSP Arch pipes show wall thicknesses that are inches thick. The circular pipes show wall thicknesses that are thin, but do not match the detailed dwg. The circular pipes appear to have the right wall thickness options. Concrete Arch pipes have a floating anchor point that corresponds to the invert elevation in the pipe properties. However, the location of the floating anchor point is between the inside and outside wall. It should be flush with the inside wall.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Cross Section Rename and Renumber Priority: MEDIUM Cross sections sheet sets can have more than 500 sheets. The rename and renumber tool within the sheet set manager requires manually typing every sheet number.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	MDT Civil 3D Subassembly and Assembly Guide-Smooth Transitions Priority: MEDIUM MDT Parameter Reference can be leveraged with using profiles to create smooth transitions in corridors. Documentation updates are needed to clarify this.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	PDF Options Priority: MEDIUM Civil 3D PDF quality options are higher than Bentley PDF options resulting in larger pdfs. Civil 3D MDT PDF (General Documentation).pc3 PDF Options include all data options.	Email Task Team	For Review



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		Pipe Network Default Parts Priority: MEDIUM Default parts aren't consistent. Default parts from DRNG parts list (Null Structure/12" RCP) are loaded in Network Layout Tools when creating or editing a pipe network. Reloading the parts list from within the Network Layout Tools dialog defaults Concentric Cylindrical Structure/15" RCP.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Plan Set Development Expediency-Road Design Typical Priority: MEDIUM Preparing typical sheet files with typical sections in model requires repetitive work setting up viewports without any automation.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Proposed Line Types Priority: MEDIUM, Complexity: MODERATE Proposed line types for some proposed features are not available.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Bentley Layer Translator-Signing Priority: MEDIUM Files converted from DGN to DWG are not appropriately mapping Bentley levels to new Civil3D layer names for Signing Data.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Section Views - Add Labels and Dynamo Scripts to State Kit for Pipe Networks Priority: MEDIUM Dynamo scripts and supporting pipe label styles are needed in State Kit to label pipe networks in section views.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Storing/Running Dynamo Scripts in State Kit Priority: MEDIUM Need file locations, content/runtime framework, supporting files, default settings, and documentation to store/run Dynamo scripts in State Kit Dynamo/Python scripts (.dyn/.py)	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Traffic Investigations Map Content Priority: MEDIUM, Complexity: COMPLEX Transportation commission traffic investigations maps require state kit development to be completed in Civil 3D.	Email Task Team	For Review



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)	TBD	Urban Scale Label Styles Priority: MEDIUM Label style scales aren't available for urban plan production.	Email Task Team	For Review
2024.4	State Kit (v2024.1.0.5)	TBD	User Palette .atc Help Guide Path Priority: MEDIUM User palette help guide is linked to path in state kit 2022 folder.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Section View Command Settings Priority: MEDIUM Cross section workflow default settings are desired.	Email Task Team	For Review
2024.4	State Kit (v2.0)	TBD	North Arrow on Layouts Priority: MEDIUM, Complexity: SIMPLE Need a dynamic north arrow with view port link.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Access Control Line Types Priority: MEDIUM, Complexity: MODERATE The access control line types include new r/w line symbology, access control symbols are too far apart, and color blue.		For Review
2024.4	State Kit (vX.XX)	TBD	Code Sets-TBC Export Priority: MEDIUM Code Set Styles are needed to support TBC export processes.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Sheet Layout Blocks on Palettes (Blocks to Palettes) Priority: MEDIUM, Complexity: MODERATE The blocks for sheet layouts are in a DWT file in the reference folder and not convenient to access.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Default Annotation Scale List Priority: MEDIUM, Complexity: MODERATE 1. Prepopulate the default annotation scale list with only scales that MDT uses.2. Add Scale list dialog box shows architectural values in dropdown menu, but adds correct engineering scales when default scale list is added with reset button.	Email Task Team	For Review



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		Disable Hardware Acceleration Priority: MEDIUM Hardware acceleration disabled notices are displaying within Civil 3D during design work.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Feature References Priority: MEDIUM Feature references need to use the construction surface references.	Email Task Team	For Review
2024.4	State Kit (vX.XX)		Geotextile Linetype Enhancement Priority: MEDIUM The hatches on the geotextile linetype (MDT_GEOTEXT) are difficult to see, display is too light.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Hydraulics Profile View - Object Style Priority: MEDIUM Hydraulics requires a screened grid profile view style.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Label Styles Priority: MEDIUM MDT process label styles are needed.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Layer Filter for Existing Utilities Priority: MEDIUM A layer filter is needed for existing utilities.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Layer for Existing Highway Easement Priority: MEDIUM New layer needed for existing highway easement.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Line Type/Block Plotting Priority: MEDIUM Line types and blocks don't always plot as desired requiring review and adjustment for desired plotting results.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	MDT C3D Styles Coordination-Corridor Styles/Command Settings Priority: MEDIUM Existing corridor style needs to be edited for MDT processes.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Measure Areas in Acres Priority: MEDIUM Need to have functionality to measure areas in acres.	Email Task Team	For Review



Civil op	C	Toward	leave	Demonto	Ctatus
Civil 3D Version	Component (Version)	Target Date	issue	Remarks	Status
2024.4	State Kit (vX.XX)		North Arrow Attributes Priority: MEDIUM The North arrow is referencing a township in the sheet set but there is not a property for township in the sheet set.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Note Label Styles Priority: MEDIUM Label style needed to label northing/easting of a polyline.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Pipe Network Label Edits Priority: MEDIUM More label styles are needed for pipe networks, specifically for plan and profile production.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Profile View Styles - Scales Priority: MEDIUM, Complexity: SIMPLE Need profile view styles for additional scales.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	R/W Layout Updates-Associated Projects Priority: MEDIUM Associated Project block displays R/W, IC, and PE numbers. Showing a P.E. number only is customary in R/W.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Sewer Parts Catalog Priority: MEDIUM A sewer parts catalogue is needed for modeling potential conflicts.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Sheet Scale Priority: MEDIUM Sheet layout scales don't support Road Design standard scales.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Sheet Set Properties Non-SSM Fields Priority: MEDIUM, Complexity: MODERATE Non-SSM fields are populated in the Sheet Set Properties.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Title Sheet Project ID Priority: MEDIUM The sheet set manager doesn't manage the title sheet project ID number.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Block Layers and Fonts: RW-Plans Priority: LOW, Complexity: COMPLEX Block layers don't follow layer naming convention or use Arial font.	Email Task Team	For Review



				· · · · · · · · · · · · · · · · · · ·	
Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		Pressure Network SSA Error Priority: LOW Storm and Sanitary Analysis is throwing errors when attempting to import a Civil3D .dwg file.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Section view label needed for existing ground crown elevation Priority: LOW A label style is needed for labeling the existing ground at the crown of the existing centerline in a section view.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Utility Plan Layer State Priority: LOW, Complexity: SIMPLE Layer state is needed to plot color utility plans.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Cadastral Survey Seal Priority: LOW MDT_SEAL_BLOCK design isn't usable for cadastral surveys.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Feature Line Styles Display Priority: LOW, Complexity: SIMPLE Display of 3D line types isn't complete through short segments.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Filters for XREF Layers Priority: LOW XREF layers are not filtered	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Land Survey Symbol Masking Priority: LOW Land Survey symbols require masking of linework beneath symbol.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Layer Color Conflicts Priority: LOW Color discrepancies and clashing are identified.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Corridor Section Editor Default Settings Priority: LOW, Complexity: SIMPLE Corridor Section Editor needs default settings.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	View Frame Sheet Template Folder Navigation Priority: LOW View frame sheet templates folder location requires user to navigate backwards in the folder structure to select a file when using the Create View Frame wizard.	Email Task Team	For Review



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)		Alias Command Priority: LOW Need documentation for users to define new alias for commands that don't have an alias assigned to them by default and/or change the existing aliases for commands to their preference. command aliases that are commonly used at MDT. The acad.pgp file can be saved in the user folder.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	MDT C3D Styles Coordination-Multileader Styles Priority: LOW Multileader styles need edits with dimension styles for consistency.	Email Task Team	For Review
2024.4	State Kit (vX.XX)		Fiber, Phone, TV Overhead Line Types Priority: LOW, Complexity: SIMPLE Existing overhead fiber and phone lines won't be used as they aren't surveyed with unique feature codes.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Existing Fiber Optic Linetype Description Priority: LOW Linetype MDT_FO_OH_E linetype description incorrectly references proposed - Fiber Optics - Overhead - Proposed.	Email Task Team	For Review
2024.4	State Kit (vX.XX)	TBD	Retain User Profile Settings w/State Kit Updates Priority: LOW, Complexity: COMPLEX < <mdt>> profile settings are wiped out when updating the State Kit. This is by design, to ensure required State Kit settings are loaded. Some profile settings can be set by the user, but cannot be saved before an update. Need a method to save a user's profile settings before an update and restore those settings after an update.</mdt>	Email Task Team	For Review
2024.4	State Kit (vX.XX)	N/A	Subassembly Side Assignment Unable to get a subassembly component to flip to the opposite side when including the MDTParameterReferences in the assembly.	Email Task Team	For Review



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)	N/A	Indirect/Related - MDT Daylight Subassembly Documentation Priority: MEDIUM, Complexity: SIMPLE Some parameter definitions are missing/need clarification for MDT Daylight subassembly in the MDT Civil 3D Subassembly and Assembly Guide.	Email Task Team Clarification added to MDT Civil 3D Subassembly and Assembly Guide for MDT Daylight subassembly.	State Kit N/A
2024.4	State Kit (vX.XX)	N/A	Indirect/Related - Cut/Fill Report unsorted Priority: LOW Cut/Fill report columns can't be sorted and produce a report with the surface volumes out of order.	Email Task Team CutFillreport.xsl edited to include sort select by name code: 1) add <xsl:sort select="@name "></xsl:sort> as line 53. Updated on MDT machines only - not included in MDT Civil 3D State Kit. [https://forums.autodesk.com/t5/civil-3d-forum/civil-3d-volumes-dashboard-sort-columns-alphabetically/m-p/6577977/highlight/true#M312853](https://forums.autodesk.com/t5/civil-3d-forum/civil-3d-volumes-dashboard-sort-columns-alphabetically/m-p/6577977/highlight/true#M312853 "smartCard-inline")	State Kit N/A
2024.4	State Kit (vX.XX)	N/A	Indirect/Related - Volume report-Select Material sheet style Priority: LOW Civil 3D won't read the select material.xsl sheet style.	Email Task Team Mass Haul - Multiple Materials.xsl and Select Material.xsl (default location: C:\ProgramData\Autodesk\C3D 2022\enu\Data\Quantities Report Style Sheets\xsl) require updates per Release Notes for Autodesk® Civil 3D® 2022.2.1 - [https://help.autodesk.com/view/CIV3D/2022/ENU/?guid=Civil3D_ReleaseNotes_2022_2_1_Release_Notes_html](https://help.autodesk.com/view/CIV3D/202 2/ENU/?guid=Civil3D_ReleaseNotes_2022_2_1_Release_Notes_html "smartCard-inline"). This patch deployed on MDT machines only. No MDT Civil 3D State Kit updates required.	State Kit N/A
2024.4	State Kit (vX.XX)	N/A	No Action - Related Projects box on Title Sheet Title sheet Related Projects box doesn't support multiple project entries.		State Kit N/A
2024.4	State Kit (vX.XX)	N/A	No Action - Transparent Commands OSnap Settings After a transparent command is used the OSnap settings are turned off.	Email Task Team OSnap settings aren't turned off when using transparent commands with Civil 3D 2024.	State Kit N/A
2024.4	State Kit (vX.XX)	N/A	No Action - Rehab Tools not Working w/State Kit Rehab Manager (Rehab Corridor Editor tab) doesn't work with a rehab corridor. It should open the Rehab Reports dialog Rehab Reports dialog loads in Imperial Civil 3D 2022 Imperial- Failure response in Civil 3D 2022 Montana State Kit Response: "Failed to start rehab manager. The region does not have a target surface.", - When setting target - Warning: "No target found in the scripts."- When attempting to create corridor by the setting number of lanes, the application crashes.	Email Task Team Rehab Manager works properly without crashing in Civil 3D 2024.	State Kit N/A



Civil 3D Version	Component (Version)	Target Date	Issue	Remarks	Status
2024.4	State Kit (vX.XX)	N/A	No Action - Admin Template Update	Email Task Team There is no solution at this time.	State Kit N/A
			Templates require local updates from BIM 360 before proceeding with development tasks.		
2024.4	State Kit (vX.XX)	N/A	No Action - Reset MDT State Kit Profile Enhancements	Email Task Team Updates in progress with request "Retain User Profile Settings w/ State Kit Updates" will resolve this issue.	State Kit N/A
			Error encountered when the MDT profile is deleted then Reset MDT State Kit Profile is used.		
2024.4	State Kit (vX.XX)		No Action - Shoulder Widening Subassembly	Email Task Team Added the acquire slope and offset from surface functions to MDT OffsetOnSurfaceLink subassembly to be released with state kit 2.0.	State Kit N/A
	(VX.XX)		Need for more control over the different shoulder slopes in MDT Widening assembly.	Added the acquire slope and offset from surface functions to MDT OffsetOnSurfaceLink subassembly to be released with state kit 2.0.	
2024.4	State Kit	Kit N/A	No Action - MDT C3D Styles Coordination-Profile		State Kit N/A
	(vX.XX)		View Styles/Command Settings	See requests "Profile view styles for split profiles" and "Profile View Band Styles" for solution.	
			Need Profile View Styles for profiles to support MDT processes.		
2024.4	State Kit	N/A	No Action - Update XS layouts	Email Task Team	State Kit N/A
	(vX.XX)		Sheet description on cross sections sheets	Create new version of B-Border-Road\ 11x17 title block for cross sections so that the DSC-1 (Sheet description) reads as "CROSS SECTIONS." Then update the border in the MDT_XS_10 and MDT_XS_20 layouts in the XS-layouts.dwt sheet template fileNo Action reasoning (Caitlyn):_ Users can use	
			needs to display as "CROSS SECTIONS".	the Find command and find and replace all instances of "####" in their drawing with their wording preference for cross sections. This allows the designer to	
			Updating the numerous sheets is tedious.	specify the mainline, approach, ramp adjective for cross sections, whereas the method above would require the user to add or edit the adjective anyway.	
2024.4	State Kit	N/A	Indirect/Related - Civil 3D 2024 Installs for 2024	Email Task Team	State Kit N/A
	(vX.XX)		Development Priority: HIGH		
			Civil 3D installs for 2024 State Kit development		
			needed. (With subassembly composer.)		