White Sulphur Springs Airport

Standards Review Nonstandard Conditions & Notes



Runway 1 / 19

1. RUNWAY LENGTH RECOMMENDED TO MEET 100% OF SMALL AIRCRAFT NEEDS (6,230 FT).
2. RUNWAY LIGHTS ARE IN VARIOUS STATE OF DISREPAIR IN THE VICINITY OF THE CROSSWIND RUNWAY INTERSECTION & THE 1 END.
3. LIGHTS WITH THE WRONG COLOR GLOBE.

Taxiways & Aprons

1. MISSING REFLECTOR.
2. MISSING PORTION OF FENCELINE.

SAFETY AREAS (RSA) (TSA)
OBJECT FREE AREAS (OFA)
RUNWAY PROTECTION ZONE (RPZ)
PAVEMENT
FENCE
ROAD
BEACON
SEGMENTED CIRCLE & WIND CONE
WIND CONE

PREPARED FOR:
WHITE SULPHUR SPRINGS, MONTANA
DATE: APRIL 1, 1996
PREPARED BY: