


This document, together with the concepts and designs presented herein, is an instrument of service, is intended only for the specific purpose and client for which it was prepared. Reuse of and improper reliance on this document without written authorization and adaptation by Kinney-Horn and Associates, Inc. shall be without liability to Kinney-Horn and Associates, Inc.



**LEGEND**

—	BRANCH IDENTIFIER
—	SECTION IDENTIFIER
—	SECTION BOUNDARY
■ (Dark Green)	PCI 86-100 GOOD
■ (Light Green)	PCI 71-85 SATISFACTORY
■ (Yellow)	PCI 56-70 FAIR
■ (Orange)	PCI 41-55 POOR
■ (Pink)	PCI 26-40 VERY POOR
■ (Red)	PCI 11-25 SERIOUS
■ (Grey)	PCI 0-10 FAILED

**CURRENT 2021 PAVEMENT CONDITION INDEX**

Branch ID	Section ID	Branch Name	Surface Type	Section Area (SF)	Approx. Age at Inspection	Last Major Work Date	Last Inspection Date	Pavement Condition Index	PCI Category
AP	01	Apron	AAC	76,125	11.3	8/1/2010	9/3/2021	91	Good
RW01	01	Runway 01-19	AAC	315,000	11.3	8/1/2010	9/3/2021	92	Good
TW	01	Taxiway	AAC	56,700	11.3	7/1/2010	9/3/2021	95	Good
TW	02	Taxiway	AC	42,000	30.1	9/30/1991	9/3/2021	94	Good
TW	03	Taxiway	AAC	60,000	11.3	7/1/2010	9/3/2021	85	Satisfactory
TW	04	Taxiway	AC	17,500	19.3	8/1/2002	9/3/2021	83	Satisfactory
TW	05	Taxiway	AC	6,200	30.1	9/30/1991	9/3/2021	86	Good

**AIRFIELD PAVEMENT WORK HISTORY**

1. AIP-003-1991, ALL NEW CONSTRUCTION
2. OWNER CONSTRUCTED
3. AIP-004, 2002, CONSTRUCT TAXIWAYS (TW:03,TW:04); CRACK SEAL, FOG SEAL, AND REMARK REMAINING PAVEMENTS.
4. AIP-011/012-2010, OVERLAY RUNWAY (RW01:01), TAXIWAYS (TW:01,TW:03) AND APRON (AP:01).
5. AIP-013-2014, CRACK SEAL, SEAL COAT, AND REMARK ALL PAVEMENTS.
6. AIP 014-2021 CRACK SEAL, SEAL COAT, AND REMARK ALL PAVEMENTS [INSPECTED AFTER MAINTENANCE PROJECT]

Runway



*RW01-01-14: Overview*



*RW01-01-62: L&T Cracking*

Taxiway



*TW01-08: L&T Cracking*



*TW04-05: Overview*

Apron



*AP01-08: L&T Cracking*



*AP01-14: Overview*

## Re-Inspection Report

MDT SASP 2021

Generated Date 12/6/2021

Page 1 of 7

**Network:** 88M **Name:** Eureka Airport

**Branch:** AP **Name:** Apron **Use:** APRON **Area:** 76,125 SqFt

**Section:** 01 of 1 **From:** ENTIRE APRON **To:** **Last Const.:** 8/1/2010

**Surface:** AAC **Family:** DEFAULT **Zone:** EURE **Category:** E **Rank:** P

**Area:** 76,125 SqFt **Length:** 290 Ft **Width:** 263 Ft

**Slabs:** **Slab Length:** Ft **Slab Width:** Ft **Joint Length:** Ft

**Shoulder:** **Street Type:** ACN **Grade:** 0 **Lanes:** 0

**Section Comments:**

**Work Date:** 9/30/1991 **Work Type:** New Construction - Initial **Code:** NU-IN **Is Major M&R:** True

**Work Date:** 8/1/2010 **Work Type:** Overlay - AC Structural **Code:** OL-AS **Is Major M&R:** True

**Work Date:** 8/23/2021 **Work Type:** Crack Sealing - AC **Code:** CS-AC **Is Major M&R:** False

**Work Date:** 8/23/2021 **Work Type:** Surface Seal **Code:** SS-LO **Is Major M&R:** False

**Last Insp. Date:** 9/3/2021 **Total Samples:** 15 **Surveyed:** 5

**Conditions:** PCI: 91

**Inspection Comments:**

**Sample Number:** 03 **Type:** R **Area:** 5075.00 SqFt **PCI:** 92

**Sample Comments:**

48 L & T CR L 117.00 Ft

**Sample Number:** 04 **Type:** R **Area:** 5075.00 SqFt **PCI:** 92

**Sample Comments:**

48 L & T CR L 106.00 Ft

**Sample Number:** 08 **Type:** R **Area:** 5075.00 SqFt **PCI:** 90

**Sample Comments:**

48 L & T CR L 159.00 Ft

**Sample Number:** 12 **Type:** R **Area:** 5075.00 SqFt **PCI:** 88

**Sample Comments:**

48 L & T CR L 197.00 Ft

**Sample Number:** 14 **Type:** R **Area:** 5075.00 SqFt **PCI:** 92

**Sample Comments:**

48 L & T CR L 112.00 Ft

<b>Network:</b>	88M	<b>Name:</b>	Eureka Airport						
<b>Branch:</b>	RW01	<b>Name:</b>	Runway 01-19	<b>Use:</b>	RUNWAY	<b>Area:</b>	315,000 SqFt		
<b>Section:</b>	01	of	1	<b>From:</b>	STA 0+00 RWY 18/36	<b>To:</b>	STA 42+00 RWY 18/36	<b>Last Const.:</b>	8/1/2010
<b>Surface:</b>	AAC	<b>Family:</b>	DEFAULT	<b>Zone:</b>	EURE	<b>Category:</b>	E	<b>Rank:</b>	P
<b>Area:</b>	315,000 SqFt	<b>Length:</b>	4,200 Ft	<b>Width:</b>	75 Ft				
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft		
<b>Shoulder:</b>		<b>Street Type:</b>	ACR	<b>Grade:</b>	0	<b>Lanes:</b>	0		
<b>Section Comments:</b>									
<b>Work Date:</b>	9/30/1991	<b>Work Type:</b> New Construction - Initial			<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True		
<b>Work Date:</b>	8/1/2010	<b>Work Type:</b> Overlay - AC Structural			<b>Code:</b>	OL-AS	<b>Is Major M&amp;R:</b> True		
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b> Surface Seal			<b>Code:</b>	SS-LO	<b>Is Major M&amp;R:</b> False		
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b> Crack Sealing - AC			<b>Code:</b>	CS-AC	<b>Is Major M&amp;R:</b> False		
<b>Last Insp. Date:</b>	9/3/2021	<b>TotalSamples:</b>	65	<b>Surveyed:</b>	7				
<b>Conditions:</b>	PCI: 92								
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	04	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	94		
<b>Sample Comments:</b>									
48	L & T CR	L	75.00	Ft					
<b>Sample Number:</b>	14	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	91		
<b>Sample Comments:</b>									
48	L & T CR	L	130.00	Ft					
<b>Sample Number:</b>	24	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	90		
<b>Sample Comments:</b>									
48	L & T CR	L	148.00	Ft					
<b>Sample Number:</b>	34	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	93		
<b>Sample Comments:</b>									
48	L & T CR	L	81.00	Ft					
<b>Sample Number:</b>	44	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	96		
<b>Sample Comments:</b>									
48	L & T CR	L	23.00	Ft					
<b>Sample Number:</b>	54	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	90		
<b>Sample Comments:</b>									
48	L & T CR	L	140.00	Ft					
<b>Sample Number:</b>	62	<b>Type:</b>	R	<b>Area:</b>	4875.00 SqFt	<b>PCI:</b>	92		
<b>Sample Comments:</b>									
48	L & T CR	L	108.00	Ft					

<b>Network:</b>	88M	<b>Name:</b>	Eureka Airport						
<b>Branch:</b>	TW	<b>Name:</b>	Taxiway	<b>Use:</b>	TAXIWAY	<b>Area:</b>	182,400 SqFt		
<b>Section:</b>	01	of	5	<b>From:</b>	APRON TO RWY 18/36	<b>To:</b>	AND TURNAROUNDS	<b>Last Const.:</b>	7/1/2010
<b>Surface:</b>	AAC	<b>Family:</b>	DEFAULT	<b>Zone:</b>	EURE	<b>Category:</b>	E	<b>Rank:</b>	P
<b>Area:</b>	56,700 SqFt	<b>Length:</b>	1,620 Ft	<b>Width:</b>	35 Ft				
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft		
<b>Shoulder:</b>		<b>Street Type:</b>	ACR	<b>Grade:</b>	0	<b>Lanes:</b>	0		
<b>Section Comments:</b>									
<b>Work Date:</b>	9/30/1991	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	7/1/2010	<b>Work Type:</b>	Overlay - AC Structural		<b>Code:</b>	OL-AS	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Surface Seal		<b>Code:</b>	SS-LO	<b>Is Major M&amp;R:</b>	False	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Crack Sealing - AC		<b>Code:</b>	CS-AC	<b>Is Major M&amp;R:</b>	False	
<b>Last Insp. Date:</b>	9/3/2021	<b>TotalSamples:</b>	12	<b>Surveyed:</b>	4				
<b>Conditions:</b>	PCI: 95								
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	02	<b>Type:</b>	R	<b>Area:</b>	5325.00 SqFt	<b>PCI:</b>	95		
<b>Sample Comments:</b>									
48	L & T CR	L	59.00	Ft					
<b>Sample Number:</b>	04	<b>Type:</b>	R	<b>Area:</b>	5075.00 SqFt	<b>PCI:</b>	96		
<b>Sample Comments:</b>									
48	L & T CR	L	23.00	Ft					
<b>Sample Number:</b>	08	<b>Type:</b>	R	<b>Area:</b>	3238.00 SqFt	<b>PCI:</b>	95		
<b>Sample Comments:</b>									
48	L & T CR	L	40.00	Ft					
<b>Sample Number:</b>	12	<b>Type:</b>	R	<b>Area:</b>	5075.00 SqFt	<b>PCI:</b>	94		
<b>Sample Comments:</b>									
48	L & T CR	L	67.00	Ft					

<b>Network:</b>	88M	<b>Name:</b>	Eureka Airport				
<b>Branch:</b>	TW	<b>Name:</b>	Taxiway	<b>Use:</b>	TAXIWAY	<b>Area:</b>	182,400 SqFt
<b>Section:</b>	02	of 5	<b>From:</b>	SOUTH T-1 TURNAROUND	<b>To:</b>	APRON	<b>Last Const.:</b> 9/30/1991
<b>Surface:</b>	AC	<b>Family:</b>	DEFAULT	<b>Zone:</b>	EURE	<b>Category:</b>	E
<b>Area:</b>	42,000 SqFt	<b>Length:</b>	1,200 Ft	<b>Width:</b>	35 Ft	<b>Rank:</b>	P
<b>Slabs:</b>	<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft	
<b>Shoulder:</b>	<b>Street Type:</b>	ACR	<b>Grade:</b>	0	<b>Lanes:</b>	0	
<b>Section Comments:</b>							
<b>Work Date:</b>	9/30/1991	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b> True
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Crack Sealing - AC		<b>Code:</b>	CS-AC	<b>Is Major M&amp;R:</b> False
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Surface Seal		<b>Code:</b>	SS-LO	<b>Is Major M&amp;R:</b> False
<b>Last Insp. Date:</b>	9/3/2021	<b>TotalSamples:</b>	6	<b>Surveyed:</b>	3		
<b>Conditions:</b>	PCI: 94						
<b>Inspection Comments:</b>							
<b>Sample Number:</b>	01	<b>Type:</b>	R	<b>Area:</b>	6971.00 SqFt	<b>PCI:</b>	94
<b>Sample Comments:</b>							
48	L & T CR	L	106.00	Ft			
<b>Sample Number:</b>	03	<b>Type:</b>	R	<b>Area:</b>	6993.00 SqFt	<b>PCI:</b>	94
<b>Sample Comments:</b>							
48	L & T CR	L	100.00	Ft			
<b>Sample Number:</b>	05	<b>Type:</b>	R	<b>Area:</b>	6993.00 SqFt	<b>PCI:</b>	94
<b>Sample Comments:</b>							
48	L & T CR	L	109.00	Ft			



<b>Network:</b>	88M	<b>Name:</b>	Eureka Airport						
<b>Branch:</b>	TW	<b>Name:</b>	Taxiway	<b>Use:</b>	TAXIWAY	<b>Area:</b>	182,400 SqFt		
<b>Section:</b>	03	of	5	<b>From:</b>	A-1	<b>To:</b>	T-1	<b>Last Const.:</b>	7/1/2010
<b>Surface:</b>	AAC	<b>Family:</b>	DEFAULT	<b>Zone:</b>	EURE	<b>Category:</b>	E	<b>Rank:</b>	P
<b>Area:</b>	60,000 SqFt	<b>Length:</b>	2,400 Ft	<b>Width:</b>	25 Ft				
<b>Slabs:</b>		<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft		
<b>Shoulder:</b>		<b>Street Type:</b>	ACR	<b>Grade:</b>	0	<b>Lanes:</b>	0		
<b>Section Comments:</b>									
<b>Work Date:</b>	8/1/2002	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	7/1/2010	<b>Work Type:</b>	Overlay - AC Structural		<b>Code:</b>	OL-AS	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Surface Seal		<b>Code:</b>	SS-LO	<b>Is Major M&amp;R:</b>	False	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Crack Sealing - AC		<b>Code:</b>	CS-AC	<b>Is Major M&amp;R:</b>	False	
<b>Last Insp. Date:</b>	9/3/2021	<b>TotalSamples:</b>	12		<b>Surveyed:</b>	4			
<b>Conditions:</b>	PCI:	85							
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	02	<b>Type:</b>	R	<b>Area:</b>	6993.00 SqFt	<b>PCI:</b>	87		
<b>Sample Comments:</b>									
48	L & T CR		L	306.00 Ft					
<b>Sample Number:</b>	05	<b>Type:</b>	R	<b>Area:</b>	6993.00 SqFt	<b>PCI:</b>	85		
<b>Sample Comments:</b>									
48	L & T CR		L	358.00 Ft					
<b>Sample Number:</b>	08	<b>Type:</b>	R	<b>Area:</b>	6993.00 SqFt	<b>PCI:</b>	85		
<b>Sample Comments:</b>									
48	L & T CR		L	357.00 Ft					
<b>Sample Number:</b>	11	<b>Type:</b>	R	<b>Area:</b>	6993.00 SqFt	<b>PCI:</b>	85		
<b>Sample Comments:</b>									
48	L & T CR		L	348.00 Ft					

<b>Network:</b>	88M	<b>Name:</b>	Eureka Airport						
<b>Branch:</b>	TW	<b>Name:</b>	Taxiway	<b>Use:</b>	TAXIWAY	<b>Area:</b>	182,400 SqFt		
<b>Section:</b>	04	of 5	<b>From:</b>	A-1	<b>To:</b>	HANGARS	<b>Last Const.:</b>	8/1/2002	
<b>Surface:</b>	AC	<b>Family:</b>	DEFAULT	<b>Zone:</b>	EURE	<b>Category:</b>	E	<b>Rank:</b>	P
<b>Area:</b>	17,500 SqFt	<b>Length:</b>	875 Ft	<b>Width:</b>	20 Ft				
<b>Slabs:</b>	<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft			
<b>Shoulder:</b>	<b>Street Type:</b>	ACR	<b>Grade:</b>	0	<b>Lanes:</b>	0			
<b>Section Comments:</b>									
<b>Work Date:</b>	8/1/2002	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Surface Seal		<b>Code:</b>	SS-LO	<b>Is Major M&amp;R:</b>	False	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Crack Sealing - AC		<b>Code:</b>	CS-AC	<b>Is Major M&amp;R:</b>	False	
<b>Last Insp. Date:</b>	9/3/2021	<b>TotalSamples:</b>	5	<b>Surveyed:</b>	3				
<b>Conditions:</b>	PCI:	83							
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	01	<b>Type:</b>	R	<b>Area:</b>	3500.00 SqFt	<b>PCI:</b>	83		
<b>Sample Comments:</b>									
48	L & T CR	L	208.00	Ft					
<b>Sample Number:</b>	03	<b>Type:</b>	R	<b>Area:</b>	3500.00 SqFt	<b>PCI:</b>	84		
<b>Sample Comments:</b>									
48	L & T CR	L	198.00	Ft					
<b>Sample Number:</b>	05	<b>Type:</b>	R	<b>Area:</b>	3500.00 SqFt	<b>PCI:</b>	81		
<b>Sample Comments:</b>									
48	L & T CR	L	248.00	Ft					

<b>Network:</b>	88M	<b>Name:</b>	Eureka Airport						
<b>Branch:</b>	TW	<b>Name:</b>	Taxiway	<b>Use:</b>	TAXIWAY	<b>Area:</b>	182,400 SqFt		
<b>Section:</b>	05	of 5	<b>From:</b>	A-1	<b>To:</b>	Hangars	<b>Last Const.:</b>	9/30/1991	
<b>Surface:</b>	AC	<b>Family:</b>	DEFAULT	<b>Zone:</b>	EURE	<b>Category:</b>	E	<b>Rank:</b>	P
<b>Area:</b>	6,200 SqFt	<b>Length:</b>	310 Ft	<b>Width:</b>	20 Ft				
<b>Slabs:</b>	<b>Slab Length:</b>	Ft	<b>Slab Width:</b>	Ft	<b>Joint Length:</b>	Ft			
<b>Shoulder:</b>	<b>Street Type:</b>	ACR	<b>Grade:</b>	0	<b>Lanes:</b>	0			
<b>Section Comments:</b>									
<b>Work Date:</b>	9/30/1991	<b>Work Type:</b>	New Construction - Initial		<b>Code:</b>	NU-IN	<b>Is Major M&amp;R:</b>	True	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Surface Seal		<b>Code:</b>	SS-LO	<b>Is Major M&amp;R:</b>	False	
<b>Work Date:</b>	8/23/2021	<b>Work Type:</b>	Crack Sealing - AC		<b>Code:</b>	CS-AC	<b>Is Major M&amp;R:</b>	False	
<b>Last Insp. Date:</b>	9/3/2021	<b>TotalSamples:</b>	2	<b>Surveyed:</b>	2				
<b>Conditions:</b>	PCI:	86							
<b>Inspection Comments:</b>									
<b>Sample Number:</b>	01	<b>Type:</b>	R	<b>Area:</b>	3100.00 SqFt	<b>PCI:</b>	87		
<b>Sample Comments:</b>									
48	L & T CR	L	126.00	Ft					
<b>Sample Number:</b>	02	<b>Type:</b>	R	<b>Area:</b>	3100.00 SqFt	<b>PCI:</b>	85		
<b>Sample Comments:</b>									
45	DEPRESSION	L	7.00	SqFt					
48	L & T CR	L	138.00	Ft					