

Photo Plate 4: Flathead River Bridge (24FH463)

Photograph 1:

Looking eastward across the existing bridge. The present structure does not meet MDT's optimal width for two-lane bridges and has a limited vertical clearance. The bridge's deteriorated conditions have resulted in the posting of a 3-ton load limit for vehicles using the structure.

