


March 2022



If you have questions regarding any this information, please contact the MDT Motor Carrier Services Division at 406-444-2998 or by email at mdtmcsirpcontact@mt.gov



PRISM is being performed in all states.



Montana Department of Transportation
Motor Carrier Services Division
2701 Prospect Ave
PO Box 4639
Helena, MT 59601
406-444-6130
<http://www.mdt.mt.gov/>



INTERNATIONAL REGISTRATION PLAN, INC

Additional information may be found regarding IRP at www.irponline.org

Alternative accessible formats of this document will be provided upon request. Please contact Motor Carrier Services at 406-444-6130 / Montana Relay 711, to request this document in a different format.

This document is printed at state expense. Information on the cost of producing this publication may be obtained by contacting the Department of Administration.



FMCSA

Federal Motor Carrier Safety Administration

Visit the FMCSA website at
<https://www.fmcsa.dot.gov>.
FMCSA may also be contacted by
phone at 1-800-832-5660.

The Montana Department of Transportation participates in the federal Performance and Registration Information Systems Management (PRISM) program.

PRISM is a partnership between the Federal Motor Carrier Safety Administration (FMCSA) and the states to promote and enhance motor carrier safety.

International Registration Plan (IRP) Changes

- IRP Checklist
- A new IRP application (Schedule A/C) form.
- A new Miles Form (Schedule B)
- Signature Page
- A new Trailer Application (Schedule C-T) (if required)
- Lease Agreement (if required)
- Power of Attorney (if required)
- A requirement for the United States Department of Transportation (USDOT) number and Taxpayer Identification Number (TIN) to be provided on these forms for each vehicle being registered. The TIN is the Federal Employer Identification Number (FEIN) or Social Security Number (SSN). These numbers are for the carrier that is responsible for the safe operation of the vehicle.
- A requirement to specify whether the carrier responsible for the safety of a vehicle is expected to change during the registration year. If the carrier is not expected to change, information about the responsible carrier is included in a bar code on the IRP registration card to assist enforcement in completing vehicle and carrier inspections.

- A requirement to update the company's census data (form MCS 150) with FMCSA every two years.
- Vehicles associated with a carrier that has been placed out of service by FMCSA will be denied IRP registration until the out of service condition has been satisfied. The same applies for vehicles that are subject to a vehicle-level out of service order.

How to Determine the Motor Carrier Responsible for Safety

The motor carrier responsible for safety (MCRS) is the entity accountable for but not limited to, hours-of-service, safety regulations, vehicle maintenance, and drug and alcohol testing.

If the IRP registrant holds the responsibility for all vehicles in the registrant's fleet, the USDOT number and TIN for the IRP registrant should be listed for each vehicle.

If the IRP registrant only rents or leases its vehicles, the USDOT number of the renter or lessee should be listed regardless if it is a short term or long-term lease.

If the IRP registrant is an owner operator that always operates under another company's interstate operating authority, the USDOT number of the carrier holding the authority should be listed regardless if it is a short term or long-term lease.

If the IRP registrant is a valid interstate motor carrier, but also rents or leases vehicles to other interstate motor carriers who will be responsible for their safe operation, the following instructions should be followed when providing the USDOT number and TIN of the carrier responsible for the safety of the individual rented or leased vehicles:

Short Term Lease – if the vehicle will be rented or leased for less than 30 days to an interstate motor carrier, enter the IRP registrant's USDOT number and TIN.

Long Term Lease – if the vehicle will be leased for 30 days or more to an interstate motor carrier, enter the lessee's USDOT number and TIN.

When a lease on a vehicle is changed to a long-term lease, a new IRP application to update the motor carrier responsible for safety, must be submitted. A replacement registration card will be issued to ensure safety related events are assigned to the proper carrier.

Actions You Should Take to Avoid Service Delays

- When filing an IRP application, ensure that you have completed the information about the motor carrier responsible for the safety of your vehicle(s).
- If the carrier responsible for the safe operation of any vehicle in a fleet does not have a USDOT number, the carrier should obtain one now. Apply online through the FMCSA website www.fmcsa.dot.gov under Registration or Licensing or contact FMCSA at 1-800-832-5660.
- If the responsible carrier has an outstanding out of service order issued by FMCSA, action should be taken to comply with the order.
- If any vehicle in your IRP fleet has an outstanding out of service order issued by FMCSA, action should be taken to comply with the order.