Colstrip Airport

Standards Review
Nonstandard Conditions & Notes



Runway 6 / 24

① NONFRANGIBLE INFORMATION SIGN IN OFA & PRIMARY SURFACE.

② TERRAIN PENETRATES ULTIMATE TRANSITIONAL SURFACE, MAY NOT PENETRATE UNDER CURRENT CONDITIONS.

③ TERRAIN PENETRATES TRANSITIONAL SURFACE.

④ BRUSH IN OFA.

⑤ TREES IN OFA & PENETRATE TRANSITIONAL SURFACE.

Taxiways & Aprons

1 ONLY ONE HOLD LINE ON JUG HANDLE.

SAFETY AREAS (RSA) (TSA)
OBJECT FREE AREAS (OFA)
RUNWAY PROTECTION ZONE (RPZ)
PAVEMENT
FENCE
ROAD
BEACON
SEGMENTED CIRCLE & WIND CONE
WIND CONE

PREPARED FOR:

COLSTRIP, MONTANA

DATE: APRIL 1, 1996

PREPARED BY: