Forsyth Airport

Standards Review
Nonstandard Conditions & Notes



Runway 8 / 26

1. TREE PENETRATES TRANSITIONAL SURFACE.
2. FENCE PENETRATES PRIMARY SURFACE OR TRANSITIONAL SURFACE IN AT LEAST TWO PLACES.
3. WIND CONE PENETRATES TRANSITIONAL SURFACE.
4. FENCE IN OFA.
5. TWO PINE TREES BRUSH BOTTOM OF APPROACH SLOPE.

Taxiways & Aprons

NONE

SAFETY AREAS (RSA) (TSA)
OBJECT FREE AREAS (OFA)
RUNWAY PROTECTION ZONE (RPZ)
PAVEMENT
FENCE
ROAD
BEACON
SEGMENTED CIRCLE & WIND CONE
WIND CONE

PREPARED FOR:

FORSYTH, MONTANA

DATE: APRIL 1, 1996

PREPARED BY: