

Granite Creek Reclamation and Realignment Project

Project Area Photos



Photo 1. Sediment deposition observed on upstream side of Highway 287 Bridge over Granite Creek



Photo 2. Photo looking upstream from Highway 287 Bridge over Granite Creek showing stream bed aggradation. .



Photo 3. Fine gravel, sand, and silt deposits beneath Highway 287 Bridge over Granite Creek.



Photo 4. Sediment deposits adjacent to Granite Creek immediately downstream of Highway 287 Bridge.